

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2
SANTA FE, NEW MEXICO

Form C-103
Revised 10-1-77

RECEIVED
JUN 20 1986

OIL CON. DIV. 1
DIST. 3

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator <i>Sunco Energy Corporation</i>	8. Farm or Lease Name <i>Sunco</i>
3. Address of Operator <i>P.O. Box 570365 Houston, Texas 77257</i>	9. Well No. <i>3</i>
4. Location of Well UNIT LETTER <i>F</i> <i>1858</i> FEET FROM THE <i>South</i> LINE AND <i>1800</i> FEET FROM THE <i>West</i> LINE, SECTION <i>14</i> TOWNSHIP <i>28</i> RANGE <i>1E</i> NMPM.	10. Field and Pool, or Wildcat <i>Wildcat Dakota</i>
15. Elevation (Show whether DF, RT, GR, etc.)	12. County

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Locate well with rods & tubing, Set pump jack and pump well to determine its potential, and fill out necessary forms.
(1) If results are poor, prepare to Stimulate Dakota.
(2) Set tubing and swap well until formation has cleared up.
(3) Set tubing and rods. Set pump jack and pump to potentiate well.
(4) If well is unproductive plug and abandon well immediately.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Ed D. L...* TITLE *Supervisor* DATE *6-18-86*

APPROVED BY *ORIGINAL SIGNED BY ERNIE BUSCH* TITLE *DEPUTY OIL & GAS INSPECTOR, DIST. #3* DATE *JUN 20 1986*

CONDITIONS OF APPROVAL, IF ANY: