UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells	
5.	SF-079729
1. Type of Well GAS GAS	If Indian, All. or Tribe Name
2. Name of Operator	Unit Agreement Name San Juan 28-4 Unit
BURLINGTON RESOURCES OIL & GAS COMPANY	
3. Address & Phone No. of Operator	. Well Name & Number San Juan 28-4 #17R
PO Box 4289, Farmington, NM 87499 (505) 326-9700 9	30-039-25381
1505'FNL, 950'FEL, Sec.20, T-28-N, R-4-W, NMPM	Choza Mesa PC/Basin FC County and State Rio Arriba Co, NM
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTH	ER DATA
Casing Repair Water Shut	uction e Fracturing off
Final Abandonment Altering Casing Conversion _X_ Other -	to Injection
13. Describe Proposed or Completed Operations	
It is intended to plug and abandon the subject well according procedure and wellbore diagram.	to the attached
	1 (3) 1 (3) 2 (8)
14. I hereby certify that the foregoing is true and correct.	
Signed Vanger Oltanama - for Title Regulatory Administrator I	Pate 9/30/99
Signed Varcy Oltmanns - for Title Regulatory Administrator I	
(This space for Federal or State Office use) APPROVED BY Chip Handen Title Ochno Englished ate CONDITION OF APPROVAL, if any:	10/18/99

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

San Juan 28-4 Unit #17R

Choza Mesa Pictured Cliffs / Basin Fruitland Coal 1505' FNL and 950' FEL, Section 20, T-28-N, R-04-W Rio Arriba Co., New Mexico Latitude / Longitude: 36°38.98134' / 107°16.06932' Recommended P&A Procedure 9/29/99

NOTE: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

- Install and test location rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and Burlington safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief-line and blow down well; kill with water as necessary. ND wellhead and NU BOP. Test BOP.
- 2. TOH and tally 2-3/8" tubing (139 jts set at 4359'); visually inspect the tubing. If necessary LD tubing and PU 2" workstring.
- 3. Plug #1 (Pictured Cliffs and Fruitland Coal perforations and tops, 4410' 3968'): TIH with open-ended tubing. Pump 40 bbls water down tubing. Mix 50 sxs Class B cement (long plug, 50% excess) and spot a plug to fill the wellbore adjacent to the Pictured Cliffs and Fruitland perforations.

 TOH and WOC, TIH and tag cement. Load casing and pressure test to 500#. If casing does not test then spot or tag subsequent plug as appropriate. PUH to 3870'.

 CAN'T SCT a Comt retainer only to between PC+ FTC PERF. Sfor PLUL+ was
- 4. Plug #2 (Kirtland and Ojo Alamo tops, 3870' 3525'): Mix 30 sxs Class B cement and spot a balanced plug inside casing to cover Kirtland and Ojo Alamo tops. PUH to 2830'.
- 5. Plug #3 (Nacimiento top, 2830' 2730'): Mix 12 sxs Class B cement and spot a balanced plug inside casing to cover Nacimiento top. PUH to 591'.
- 6. Plug #4 (8-5/8" Casing shoe at 541"): Mix 45 sxs Class B cement and spot a balanced plug inside casing to cover casing shoe to surface, circulate cement out casing valve. TOH and LD tubing.

7. ND BOP and cut off wellhead below surface casing. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.

Recommended:

Operations Engineer

Approved:

Drilling Superintendent

San Juan 28-4 Unit #17R

Current

Choza Mesa Pictured Cliffs/Basin Fruitland Coal NE, Section 20, T-28-N, R-4-W, Rio Arriba County, NM

Latitude/Longitude: 36 - 38.98134'/107 - 16.06932'

Today's Date: 9/28/99 Spud: 8/4/94 Comp: 9/27/94 Elevation: 7330' GR

12-1/4" Hole

8-5/8" 24#, K-55 Casing set @ 541' 460 cf cement (Circulated to Surface)

Nacimiento @ 2780'

Ojo Alamo @ 3575'

Kirtland @ 3820'

Fruitland @ 4018'

Pictured Cliffs @ 4207'

- 2-3/8" Tubing set at 4359' (139 joints, F nipple at 4326')

Fruitland Coal Perforations: 4137' - 4189'

Pictured Cliffs Perforations: 4209' - 4360'

7-7/8" Hole

TD 4545'

PBTD 4492'

4-1/2" 10.5#, K-55 Casing Set @ 4537' Cemented with 785 sxs (978 cf) Circulated cement to surface

San Juan 28-4 Unit #17R

Proposed P & A

Choza Mesa Pictured Cliffs/Basin Fruitland Coal NE, Section 20, T-28-N, R-4-W, Rio Arriba County, NM

Latitude/Longitude: 36 - 38.98134'/107 - 16.06932'

Today's Date: 9/28/99 Spud: 8/4/94 Comp: 9/27/94

Elevation: 7330' GR

12-1/4" Hole

8-5/8" 24#, K-55 Casing set @ 541' 460 cf cement (Circulated to Surface)

> Plug #4 591' - Surface, Cmt with 45 sxs Class B

Nacimiento @ 2780'

Ojo Alamo @ 3575'

Kirtland @ 3820'

Fruitland @ 4018'

Pictured Cliffs @ 4207

PBTD 4492

Plug #3 2830' - 2730' Cmt with 12 sxs Class B

Plug #2 3870' - 3525' Cmt with 30 sxs Class B

Plug #1 4410' - 3968' Cmt with 50 sxs Class B (long plug, 50% excess)

Fruitland Coal Perforations: 4137' - 4189'

Pictured Cliffs Perforations: 4209' - 4360'

7-7/8" Hole

TD 4545'

4-1/2" 10.5#, K-55 Casing Set @ 4537' Cemented with 785 sxs (978 cf) Circulated cement to surface