

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-078391-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hanson

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Gallup-Gallup

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 36, T27N, R13W

NMPLM

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

El Paso Products Company

3. ADDRESS OF OPERATOR

P. O. Box 1560, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1700'/N, 800'/W, Sec. 36, T 27N, R 13W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5974' OR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Start Operations 8-12-68

Finish Operations 8-14-68

1. Load hole with mud laden fluid.
2. Squeeze Gallup perforations at 5118' to 4899', 25 sx cmt.
3. Shoot pipe loose at free point 1289' and pull.
4. Spot 30 sx cmt, 4% gel at 1341' to 1195' in and out of stub.
5. Spot 30 sx cmt, 4% gel at 1252' to 1142' top of Pictured Cliffs.
6. Ojo Alamo behind surface casing.
7. Spot 10 sx cmt plug top surface casing with welded marker in place.
8. Clean location.

18. I hereby certify that the foregoing is true and correct

Original SIGNED by: **Jim Payne**

TITLE **Agent**

DATE **August 29, 1968**

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

RECEIVED

SEP 27 1968

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

1700-17, 000 11-11-19-17

66-27-17-137

89743K

San Juan New Mexico

Check of the Box To Measure Nature of Wells, Report, or Other Data

Box of Information

Box of Information

WATER WELL PROPORTION	WATER WELL CASING	WATER STRUCTURE	WATERING MARK
WATERING MARK	WATERING MARK	WATERING MARK	WATERING MARK
WATERING MARK	WATERING MARK	WATERING MARK	WATERING MARK
WATERING MARK	WATERING MARK	WATERING MARK	WATERING MARK

1. Head hole with mud fluid.
2. Dynamic falling performance.
3. 100' pipe holes at free point and pull.
4. 100' cement plug 50' in and 50' out of hole.
5. 100' cement plug across top of pressure cliff.
6. 100' cement plug at base of Ojo Alamo.
7. Place cement plug in top of surface with welded marker in place.
8. Clean location.

ILLEGIBLE



RECEIVED

MAR 29 1968

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

John R. Pope

Agent