OIL CONSERVATION COMMISSION

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO

November 17, 1961

Mr. William C. Mussell
R & G Drilling Company
12 West 72nd Street
New York 19, N.Y.

Dear Mr. Russell:

A recent field inspection was made of your lease equipment on the Narron #42. The following discrepancies were noted:

Liquids commingled on the location and leaking valves. Rule 303 prohibits commingling of products from two or more pools prior to measurement. Rule 115 requires well head equipment to be maintained in good working order.

Please cause these conditions to be corrected on this well prior to the Mesaverde flow period of the current packer leakage test. If similar conditions exist on other well, they should be corrected immediately.

If we can be of further service, please contact us.

Yours very truly

A. R. Kendrick Engineer, District #3

ARK: ks

cc: Production Equipment Inc. Farmington, N.M.

OCC. Santa Fe, N.N.

DIL CONSERVATION COMPLESCO

CAUD GONAPP GUA GONE

ATTE TO SET WEEKER

 $(v_{ij}) = v_{ij}^{*}(v_{ij}) \qquad \qquad v_{ij}^{*}(v_{ij}) = v_{ij}^{*}$

and the second s

作家 - Tourne Community (Applied Community Com

the state of the second se

Section Section Section 5

is an increase of the second second second

 $|x|=|\hat{y}|=|x||_{L^{\infty}(\mathbb{R}^{n})}+|x||_{L^{\infty}(\mathbb{R}^{n})}+|x||_{L^{\infty}(\mathbb{R}^{n})}$