# District I R.O. Box 1930, Holbbs, NM Ener District II P.O. Drawer DD Alesla, NM 88211 DIFFITACOLITY 1000 Rio Brazos Rd, Azlec, NM 87410 APR 1) 8 1997

State of New Mexico SUBMIT 1 COF Energy, Minerals and Natural Resources Department APPROPRIATE

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

nerals and Natural Resources Department

SUBMIT 1 COPY TO APPROPRIATE DISTRICT OFFICE AND 1 COPY TO SANTA FE OFFICE

(Revised 3/9/94)

#### PIT REMEDIATION AND CLOSURE REPORT


Operator: BONNI	EVILLE FUELS CORPORATION	Telephone	2: 303-863-1555		
Address: 1660 Lincoln Street, Suite 1800, Denver, CO 80264					
Facility Or: S	SCOTT "E" FEDERAL #13	7			
Location: Unit or Qtr/Qtr sec NW-SW L sec 24 T 27 R 11 County SAN JUAN					
Pit Type: Separator XX Dehydrator Other TANK DRAIN PIT					
Land Type: BLM_XX_, State, Fee, Other					
	Pit dimensions: lengtl	15 , width 15	, depth8		
(Attach diagram)	Reference: wellhead	, other	See Attached		
	Footage from reference				
Direction from reference: Degrees East North					
			of West South		
Depth To Ground Water: (vertical distance from contaminants to seasonal high water elevation of			(20 points) t (10 points) feet (0 points) 0		
Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources)		DECENSOR 1 8 1937	Yes (20 points)		
		OH GEN. DIV.	No (0 points) <u>0</u>		
		DWE. 3			
Distance To Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches)		Less than 200 fee 200 feet to 1000	feet (10 points)		
		Greater than 1000 RANKING SCORE	feet (0 points) C (TOTAL POINTS): C		

Date Remediation Sta	rted: 9/07/94	Date Completed: 9/07/94	
Remediation Method: (Check all appropriate	Excavation XX	Approx. cubic yards66	
sections)	Landfarmed	Insitu Bioremediation	
	Other		
	Of Remedial Action:	Contamination was remediated by dilution  nto remediated pit. A helpw grade fiberglass	
tank was emplaced in the	same location as old e	arthen pit as per NMOCD guidelines. Pit was	
bottom of pit and backfi	ll composite. Sampling	tial remediation to supply BTEX values for was done with a truck mounted Geoprobe which	
		emediated pit. Several samples were taken off as representative of the backfill. The TD	
at this site varying bet 8' in the center, but th	ween right at the surfa	with a split spoon. Bedrock is highly irregunce to 14'. The original excavation went to ill past 4'.	
Ground Water Encount	ered: No XX Yes	Depth	
Final Pit: Closure Sampling: (if multiple samples,	Sample location <u>See Attached</u>		
attach sample results and diagram of sample	Sample depth 8'; 4'		
locations and depths)	Sample date 9/07/94; 5-22-96 Sample time 0:30:00; 12:30		
	Sample Results		
	Benzene (ppm)		
	Total BTEX (pp	π)	
	Field headspace	e (ppm) <u>Composite and TL 4'</u> (PID), 6.4 units)	
	TPH @ 8'=628;	Backfill=410,362	
Ground Water Sample:	Yea No XX	(If yes, attach sample results)	
I HEREBY CERTIFY THA		BOVE IS TRUE AND COMPLETE TO THE BEST	
DATE 10/19/22	- L MK		
SIGNATURE	VERINTED M.	AME James O. Cable  Vice President Operations	

FINAL PIT CLOSURE SAMPLING REPORT

Telephone: (505) 632-9876 Operator: BONNEVILLE FUELS CORPORATION Address: 310 NORTH FIRST STREET, BLOOMFIELD, NM 87413 Facility Or: SCOTT "E" FEDERAL #13 Well Name T 27 Location: Unit or Qtr/Qtr Sec SW SIDE VIEW TPII Depth 2130 ppm Surface 2 ft. ppm 4 N. 1340 ppm 2130 ppm ppm 6 ft. 8 N. 628 ppm 10 ft. ppm ppm 12 ft. 1340 ppm 14 N. ppm 16 ft. ppm 18 N. ppm ppm 20 ft. 628 ppm N. ppm ppm N. ppm ft. TOP VIEW 15 ft. North Side 171 ppm 171 ppm East Side 244 ppm 139 ppm South Side West Side 196 ppm W)196ppm 244 ppm (E 15 ft. North (S)139 ppm

## BONNEVILLE FUELS CORPORATION SCOTT "E" FEDERAL #13



### ON SITE TECHNOLOGIES, LTD. P.O. BOX 2606, FARMINGTON, NM 87499 (505) 325-5667

DATE: 05-22-96

CLIENT: BONNEVILLE FUELS

SITE LOCATION:

SCOTT "E" FEDERAL . # 13

Unit L Sec. 24, T27N, R11W, NMPM

San Juan County

CONTRACTOR: ON SITE

EQUIPMENT: GEOPROBE (2" AUGER w/ Split Spoon)

ASSESSMENT SUMMARY

().#: B0N 100 1 .108 #: 4-1286 LOGGER: BC
PAGE #: 1

S1 ART 11:15

F IN ISH: 12:30

#### NOTES:

Two pit assessed:Blowdown/Tank Drain

Blowdown Composite: 5'- 10' (PID: 72.5 Units)

Blowdown Grab: 14' (PID: 1800 Units)

TD: 14'

Tank Drain Composite: 4' (PID: 6.4 Units)

TD: 4

