Form 3160-5 (November 1983) (Formerly 9-331)	UNITED STATES DEPARTMENT OF THE INTER BUREAU OF LAND MANAGEME		5. LEASE DESIGNATION AND SERIAL NO.
	ORY NOTICES AND REPORTS orm for proposals to drill or to deepen or plus use "APPLICATION FOR PERMIT—" for such		SF -078356 6. IF INDIAN ALLOTTER OR TRIBE NAME
OIL GAS C		1 0 5 1 1 Ac	7. DAIT AGREEMENT NAME
WELL WELL	OTHER	1114.90	Huerfanito Unit
2. NAME OF CPERATOR	P.1 Dage Water 1 PARMING	UN KESOUROS AREA	S. PARK OR LEASE NAME
3. ADDRESS OF OPERATOR	El Paso Natural Gas Con	npany ii MEXICO	Huerfanito Unit
	Post Office Box 4289.Fa	erminaton NM 87499	88
Post Office Box 4289 Farmington NM 87499 4. LOCATION OF WELL (Report location clearly and in secondance with any State requirements.* See also space 17 below.)			10. FIELD AND POOL, OR WILDCAT
At surface	800'N, 1500'E		Blanco MV/Basin Dk
			11. SEC., T., R., M., OR SLE. AND SURVEY OR AREA
			Sec.23,T-27-N,R- 9-W
14. PERMIT NO.	15. SLEVATIONS (Show whether	DF, RT, GR, etc.)	N M P M 12. COUNTY OR PARISH 13 STATE
	6	108'GL	
16.			
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data			
TEST WATER SHUT-OFF			DERT ERFORT OF:
FRACTURE TREAT	PULL OR ALTER CASING MULTIPLE COMPLETE	WATER SHUT-CFF	ESPAIRING WELL
SHOOT OR ACIDIZE	ABANDON*	FRACTURE TREATMENT SHOOTING OR ACIDIZING	ALTERING CASING ABANDONMENT®
REPAIR WELL	CHANGE PLANS	(Other)	
	ed procedure OMPLETED OPERATIONS (Clearly state all pertine ell is directionally drilled, give subsurface loc	Completion or Recomp	of multiple completion on Well eletion Report and Log form.)
Release (521' ceme 6251-5500 5503-5600 TIH w/pki Verde. I sx to 435 Spot 829 cmt. Go Drillable (top outs plug over Pull free on Dk cso stubs. Lo 277' to co	dended to plug and abang Guiberson VI pkr on Dk ent plug over Dk-Greenh by with 9.2 mud. Spot by w/35 sx. cement. TOO a look to sy w/6 sx.cmt. & look to sy w/1" look to sy w/1" look to sy w/17 sx. Fill to Pic.Cliffs, Fruitland epoint on Mesa Verde csy & shoot off. Spot 200 and hole w/9.2 mud to look to surface w/22 sx. cmt	side. TOOH & lay orn from TD to 625 100' cement plug o H. Wireline shoot pkr @ 4200'. Est squeeze Mesa Verde e pkr & fill csg 4, Fruitland & base DP & 2" drag bit & et. Spot cmt plug csg w/9.2# mud to & Ojo Alamo base g, shoot off & rec' cmt (74 sx) in 8 377'. Spot 81 sx. Load hole w/270 b	down pkr. TIH & spot 1'. Fill casing ver Gallup top from two holes @ 4496'. ablish rate into Mesa w/2 sx. Displace 4 350-2122' w/9.2# mud. of Ojo Alamo w/24 sx. clean out to TD. Mesa Verde TD to 3900' 2122'. Spot 829' cmt w/24 sx. TOOH & LD 1". over. Pull freepoint 3/4" hole to cover cmt in 9" hole 377- bls. 9.2# mud to 50'
	foregoing is true and correct		APPROVED
SIGNED SIGNY	TITLE D	rilling Clerk	DATE11-18-87
(This space for Federal	or State office use)	Nova	\$ /M
APPROVED BYCONDITIONS OF APPR	*See Instruction:	on Reverse Side	FARMINGTON RESOURCE AREA