UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

				27.70.20	5.	Lease Number
			á	E. P. CI CO CA 30	C	SF-078421
Type GAS	of Well				6.	If Indian, All. or Tribe Name
OAL	,			FEB 2001 `	يدار ا	
			\	RECEIVED	7.	Unit Agreement Nam
	of Opera		26.8	OIL CON, DIV	5)	
RE	RLU SOU	RCES	& GAS COMPANY	۵.	1	
		OID	a dan committee	S/61 CL 21 11 M S	8.	Well Name & Number
Addres	ss & Ph	one No. of Opera	itor	0700	٥	McAdams #5 API Well No.
PO Bo	ox 4289	, Farmington, N	1 87499 (505) 326	5-9700	9.	30-045-06411
Locati	ion of	Well, Footage, S	Sec., T, R, M		10.	Field and Pool
950'Fi	NL, 890	'FWL, Sec.20, T-	-27-N, R-9-W, NMPN	1	11	Basin Dakota
					11.	County and State San Juan Co, NM
			DICATE NATURE OF		T, OTHER	DATA
Type o	of Subm		Type Abandonment	of Action	ge of Pla	ans
	_ Noti	ce of Intent	Abandonment	on — New	Ge of Fig Construc	
Х	Subs	equent Report	Plugging Ba	ack Non-	Routine :	Fracturing
	_	1 71	Casing Repa	air Wate asing Conv	r Shut o	ff Thiestian
	_ Fina	l Abandonment	X Other - Ti	ubing <u> </u>	ersion c	J Injection
						<u> </u>
. De:	scribe	Proposed or Comp	oleted Operations			
			oleted Operations			
2-:	scribe 2-01 5-01	MIRU. ND WH. NO	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/mi	/8" tbg. SDON.	t ret @	6510'. SDON.
2-: 2-: 2-:	2-01 5-01 6-01	MIRU. ND WH. NO PT csg to 500 p	Deted Operations J BOP. TOOH w/2 3, DSI, OK. TIH w/mi E @ 6510'. SDON.	/8" tbg. SDON.		6510'. SDON.
2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01	MIRU. ND WH. NO PT csg to 500 pmill on cmt remail cmt ret @	Deted Operations J BOP. TOOH w/2 3, DSI, OK. TIH w/mi 1 @ 6510'. SDON. 6510' to 6528'.	/8" tbg. SDON. 11. Mill on cm	DON.	
2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6	Dieted Operations J BOP. TOOH w/2 3, DSI, OK. TIH w/mi 1 @ 6510'. SDON. 6510' to 6528'. Stools. Catch fish 371'. Circ & CO to	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929'	DON. ng tools . TOOH w	& fish. SDON. /bit. TIH w/219
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8"	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/min t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, se	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929'	DON. ng tools . TOOH w	& fish. SDON. /bit. TIH w/219 WH. SDON.
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/min t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, se	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929'	DON. ng tools . TOOH w	& fish. SDON. /bit. TIH w/219 WH. SDON.
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8"	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/min t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, se	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929'	DON. ng tools . TOOH w	& fish. SDON. /bit. TIH w/219 WH. SDON.
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8"	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/min t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, se	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929'	DON. ng tools . TOOH w	& fish. SDON. /bit. TIH w/219 WH. SDON.
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8"	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/min t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, se	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929'	DON. ng tools . TOOH w	& fish. SDON. /bit. TIH w/219 WH. SDON.
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8"	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/min t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, se	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929'	DON. ng tools . TOOH w	& fish. SDON. /bit. TIH w/219 WH. SDON. 2001 FEB 20
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8"	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/min t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, se	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929'	DON. ng tools . TOOH w	& fish. SDON. /bit. TIH w/219 WH. SDON. 2001 FEB 20 PM
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8"	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/min t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, se	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929'	DON. ng tools . TOOH w	& fish. SDON. /bit. TIH w/219 WH. SDON. 2001 FEB 20 PM 5:
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8"	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/min t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, se	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929'	DON. ng tools . TOOH w	& fish. SDON. /bit. TIH w/219 WH. SDON. 2001 FEB 20 PM
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8"	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/min t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, se	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929'	DON. ng tools . TOOH w	& fish. SDON. /bit. TIH w/219 WH. SDON. 2001 FEB 20 PM 5:
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8"	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/min t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, se	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929'	DON. ng tools . TOOH w	& fish. SDON. /bit. TIH w/219 WH. SDON. 2001 FEB 20 PM 5:
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01 12-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8" RD. Rig release	pleted Operations J BOP. TOOH w/2 3, psi, OK. TIH w/mi t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, seed.	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929' t @ 6846'. ND	DON. ng tools . TOOH w BOP. NU	& fish. SDON. /bit. TIH w/219 WH. SDON. 2001 FEB 20 PM 5:
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01 12-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8" RD. Rig release	Deted Operations J BOP. TOOH w/2 3, DSi, OK. TIH w/min t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, se	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929' t @ 6846'. ND	DON. ng tools . TOOH w BOP. NU	& fish. SDON. /bit. TIH w/219 WH. SDON. 2001 FEB 20 PM 5:
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01 12-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8" RD. Rig release	pleted Operations J BOP. TOOH w/2 3, psi, OK. TIH w/mi t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, seed.	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929' t @ 6846'. ND	DON. ng tools . TOOH w BOP. NU	& fish. SDON. /bit. TIH w/219 WH. SDON. 2001 FEB 20 PM 5: 03
2-: 2-: 2-: 2-: 2-: 2-	2-01 5-01 6-01 7-01 8-01 9-01 12-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8" RD. Rig release	pleted Operations J BOP. TOOH w/2 3, psi, OK. TIH w/mi t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, seed.	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929' t @ 6846'. ND	DON. ng tools . TOOH w BOP. NU	& fish. SDON. /bit. TIH w/219 WH. SDON. 700 FEB 20 PM 5: 03
2-: 2-: 2-: 2-: 2-: 2-:	2-01 5-01 6-01 7-01 8-01 9-01 12-01	MIRU. ND WH. NO PT csg to 500 p Mill on cmt re Mill cmt ret @ TIH w/fishing TIH w/bit to 6 jts 2 3/8" RD. Rig release	pleted Operations J BOP. TOOH w/2 3, psi, OK. TIH w/mi t @ 6510'. SDON. 6510' to 6528'.' tools. Catch fish 371'. Circ & CO to 4.7# J-55 tbg, seed.	/8" tbg. SDON. 11. Mill on cm TOOH w/mill. S . TOOH w/fishi o PBTD @ 6929' t @ 6846'. ND	DON. ng tools . TOOH w BOP. NU	& fish. SDON. /bit. TIH w/219 WH. SDON. 200 FEB 20 PM 5: 03