

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF-078100-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Bayview-Riddle Gas Com

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

NE/NE Sec 18, T27N, R12W

1. OIL WELL CAR WELL OTHER

2. NAME OF OPERATOR
Amoco Production Co.

3. ADDRESS OF OPERATOR
2325 E. 30 St., Farmington, NM 87401

RECEIVED

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

NOV 17 1986

825' FNL x 1190' FEL

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5767' KB

12. COUNTY OR PARISH

San Juan

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other) Status on Repair

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Moved in and rigged up service unit on 7-11-85. Released rig on 7-11-85. Repair was delayed because well needed to produce in order to hold the lease. The repair will not be performed in the near future due to budget restraints.

NOTE: This sundry is in response to file letter 3162.3-1.0(016) dated 11-7-86.

RECEIVED
NOV 21 1986
OIL CON. DIV.
DIST. 9

18. I hereby certify that the foregoing is true and correct

SIGNED

BSShaw

TITLE Adm. Supervisor

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

NOV 20 1986

CONDITIONS OF APPROVAL, IF ANY:

FARMINGTON RESOURCE AREA

BY

Smm

*See Instructions on Reverse Side

NMOCC