Form 9-331 a (Feb. 1961)

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Budget Bureau No. 42-R358.4. Form Approved.

Land Office Santa Pe, N.M.

Lease No. NM 03151

Unit Pederal Dakota Unit 3-S

						
NOTICE OF INTER	NTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF			X
NOTICE OF INTENTION TO CHANGE PLANS			SUBSEQUENT	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING		
NOTICE OF INTENTION TO TEST WATER SHUT-OFF			SUBSEQUENT REPORT OF ALTERING CASING			
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL			SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.			
	NTION TO SHOOT OR ACI		1	REPORT OF ABANDON	177	
ł	NTION TO PULL OR ALTE		SUPPLEMENT	ARY WELL HISTORY		
NOTICE OF INTE	NTION TO ABANDON WEL	L				
	(INDICATE A	BOVE BY CHECK MARK	NATURE OF REPOR	T, NOTICE, OR OTHER E	DATA)	
	September 5				·	, 19 62
Well No	is located	790 ft. from	$n_{-}\begin{cases} \mathbf{N} \\ \mathbf{S} \end{cases}$ line and	790 ft. from	$\mathbf{m} \left\{ egin{array}{c} oldsymbol{\mathbb{R}}^{\mathbf{x}} \ \mathbf{w} \end{array} ight\}$ line of sec	. 3
SW/4. Se		T 27N	R12W	NMPM	(**)	
	id Sec. No.)	(Twp.)	(Range)	(Meridian)		
Basin Dako	•	San Juan		•	Mexi co	
	leld)		or Subdivision)		(State or Territory)	
	nd expected depths to obj	ective sands; show siz ing points, and all c	other important pro	ngths of proposed casi: sposed work)		
Spudde & ceme Re-cem	ed at 8:00 A.M. ented w/ 225 sinented w/ 100 i	octive sands; show size ing points, and all constants. On 8-3-62. ks. Neat w/ 2.	Set 8-5/8 Cement circ	", 24# J-55 ement liked ulated. W.O.	casing at 332	•
Spudde & ceme Re-cem Tested	ed at 8:00 A.M. ented w/ 225 si sented w/ 100 i i casing w/ 600 hat this plan of work mu Tidewater (ective sands; show size ing points, and all constants. on 8-3-62. ks. Neat w/ 2 sks. Neat. Off for 30 min	Set 8-5/8 2% CaCl. C Cement circ ns., no dro	", 24# J-55 ement liked ulated. W.O., p in pressure	SEP11 1962 OIL CON. CO. DIST. 3	menced.
Spudde & ceme Re-cem Tested I understand the	ed at 8:00 A.M. ented w/ 225 sl mented w/ 100 sl i casing w/ 600 hat this plan of work mu Tidewater sl	ective sands; show size ing points, and all constants. on 8-3-62. ks. Neat w/ 2 sks. Neat. Off for 30 min	Set 8-5/8 2% CaCl. C Cement circ ns., no dro	", 24# J-55 ement liked ulated. W.O., p in pressure	SEP11 1962 OIL CON. CO DIST. 3 operations may be com	menced.