

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office
078936
Lead 1/4 Section 8
T-27N, R-12E
S-27E

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 14 51

19

Well No. 2 Thompson is located 990 ft. from [N] line and 990 ft. from [E] line of sec. 8
1/4 of section 1, T-27 N, R-12 E
(1/4 Sec. and Sec. No.) (Township) (Range) (Meridian) New Mexico
San Juan County (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. (To be furnished later)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The objective sand is the Pictured Cliffs. The top is expected at about 1675'. The producing string will be 5-1/2" casing, which will be cemented. Surface casing, drilling casing, and production string will be set if and where needed approximately as follows:

90' of 5-1/2" C.C. cemented to surface. 1675' of 5-1/2" C.C. cemented with approximately 100 sacks.

Well to be drilled with rotary tools to top of Pictured Cliff sand. Casing will be set and well drilled into pay zone with cable tools. The well will then be shot with approximately 150 quarts of nitroglycerine.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company
Address
115 First National Bank Building
Durillo, Texas

By *Richard L. Landon*
Title *Managing Partner*

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
UNITED STATES
(SUBMIT IN TRIPLICATE)

NOI TAVRE MOO DO
MOISSA MOO

SUNDREY HOLICHOFF AND REPORTS ON WELLS

.....	SUBSEQUENT REPORT OF WATER SHORTAGE
.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDING
.....	SUBSEQUENT REPORT OF ALTERING CANALS
.....	SUBSEQUENT REPORT OF REBUILDING OR REMOVAL
.....	SUBSEQUENT REPORT OF ABANDONMENT
.....	SUPPLEMENTARY WELL HISTORY

(THIS PAGE MAY BE CONTINUED ON OTHER DATA)

[illegible]

(b) _____ at level six avoids need for additional materials, etc.

DEGREE OF WORK

[illegible]

I was waiting for this plan of work to receive approval, I waited by the clock for it, and before midnight I had

Copyright


...a29b5A



Company Danube Oil Co.
Lease Thompson-Federal Well No. 2
Sec. 2 T. 27 N, R. 12 W, N.M.P.M.
Location 990' from the South line,
990' from the East line.

San Juan County

New Mexico



Scale—4 inches equals 1 mile.

This is to certify that the above plat was prepared from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

Seal:

Registered Professional Charles J. Finklea
Engineer and Land Surveyor. N. Mex. Reg. No. 1302

Surveyed June 14, 1951