

F. Loc. 1750/S; 990/E Elev. 5790 DF Spd 10/4/52 Comp 12/30/52 D 1473 PR

Casing 9-5/8 @ 90 W 60 Sx. Int. @ W Sx. Pr. 6-5/8 1403 W 200 Sx. T. @

Csg. Perf. Prod. Stim. Shot 140 qts 1414-1473

I.P. 2658 ^{ROV} MCF/D After 3 Hrs. Sic. P. 435 PSI After 7 Days GOR Grav. Ist Det 2/10/53 T F R U S P H C

TOPS	NTTD	X	Well Log	X	TEST						DATA		
					Sched.	PC	Q	PW	PD	D	Alt.		
Kirtland	C-102		Plat	✓									
Fruitland	C-103		Electric Log										
Pictured Cliffs	1397	C-104	X	C-110	X	373	442	229	187	514			
Cliff House			Remarks										
Menefee			Formerly Lilly #4										
Point Lookout													
Mancos													
Tochito													
Dakota													
Morrison													
Entrada													

P W. Kutz PC Co. San Juan s 4 T 27N R 12W U T Oper. Ben & Mo Inc. GGU No. 64