Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

_	Empires, 11016
j.	Lease Serial No.
•	NMSE-078902

	SUNDRY NOTICES AND REPORTS ON WELLS				
Do not use this abandoned well.	NMSF-078902 6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPI	LICATE - Other instruc	tions on reverse side.		7. If Unit or CA/Agree	ement, Name and/or No.
1. Type of Well	8. Well Name and No.	ADVON LINET 0.47			
Oil Well Gas Well Other	<u> </u>		GALLEGOS CANYON UNIT 247		
 Name of Operator AMOCO PRODUCTION COMP 	CHERRY HLAVA E-Mail: hlavati@bp.com				
Ba. Address P.O. BOX 3092 HOUSTON, TX 77253	3b. Phone No. (include area code) Ph: 281.366.4081/ Fx: 281.366.0700		If. Field and Pool, or Exploratory BASIN DAKOTA		
4. Location of Well (Footage, Sec., T.,		and a manufacture	11. County or Parish, and State		
Sec 5 T27N R12W Mer NENE 7			SAN JUAN COUNTY, TX		
12. CHECK APPRO	OPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, RE	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	☐ Acidize	☐ Deepen	☐ Producti	on (Start/Resume)	☐ Water Shut-Off
Notice of Intent	☐ Alter Casing	□ Fracture Treat	☐ Reclama	ition	■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recomp	lete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Tempora	arily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water D	pisposal	
determined that the site is ready for fina	al inspection.)	d only after all requirements, inclu	-		
	al inspection.) quests permission to plu	g and abandon the subject v	well as per the	,	
determined that the site is ready for final Amoco Production Company red Should you have any technical of Cherry Hlava @281-366-4081	al inspection.) quests permission to plu questions please contac questions please contac que and correct. Electronic Submission #	g and abandon the subject v	well as per the	nistrative concerns p	
determined that the site is ready for final Amoco Production Company red Should you have any technical of Cherry Hlava @281-366-4081	al inspection.) quests permission to plu questions please contac questions please contac rue and correct. Electronic Submission # For AMOCO PROL Committed to AFMS	g and abandon the subject of the Allen Kutch @281-366-795 and the subject of the Allen Kutch @281-366-795 and the subject of t	well as per the	System n 1 ()	
Amoco Production Company red Should you have any technical of Cherry Hlava @281-366-4081	al inspection.) quests permission to plu questions please contac questions please contac rue and correct. Electronic Submission # For AMOCO PROL Committed to AFMS	g and abandon the subject of the Allen Kutch @281-366-795 and the subject of the Allen Kutch @281-366-795 and the subject of t	well as per the	System n 1 ()	
Amoco Production Company red Should you have any technical of Cherry Hlava @281-366-4081 4. Thereby certify that the foregoing is transport (Printed/Typed) CHERRY H	quests permission to plu questions please contac questions please contac que and correct. Electronic Submission # For AMOCO PROE Committed to AFMS	g and abandon the subject of the Allen Kutch @281-366-795 of the BLM Well of t	Vell as per the interest of th	System 1 () ESENTATIVE	
Amoco Production Company red Should you have any technical of Cherry Hlava @281-366-4081 14. I hereby certify that the foregoing is transported to the Name (Printed/Typed) CHERRY H	quests permission to plu questions please contac questions please contac que and correct. Electronic Submission # For AMOCO PROE Committed to AFMS	g and abandon the subject of the Allen Kutch @281-366-795 of the BLM Well of t	Vell as per the interest of th	System 1 () ESENTATIVE	olease contact

** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL **

SJ Basin Well Work Procedure

Well Name: GALLEGOS CANYON UNIT #247

Version:

Date: SEPTEMBER 19, 2001

Budget:

Repair Type: PLUG & ABANDON

SAP Code:

Objective: P&A WELL

- 1. TOH and strap 5956' 2 3/8".
- 2. Set cement plugs.
- 3. Cut off wellhead & install dry hole marker.

Pertinent Information:

Location:

T27N-R12W-Sec5

API #: 30-045-11678

County:

Horizon:

San Juan

FlacWell: Engr:

State: Ne

New Mexico Basin Dakota

Procedure:

- 1. Check anchors. MIRU.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down well. If necessary, kill with fresh water.
- 4. Nipple down WH, NU BOPs. Pressure test to 500 psi.
- 5. TOH and strap 5956' of 2 3/8" tbg.
- 6. RU wireline and set 4 ½" CIBP at 5900'. TIH with tbg open ended to 5900'.
- 7. Pressure test csg to 500 psi for 15 minutes. Plug #1 (5752' 5900'), balance 12 sx Cl. B cement inside csg. PUH to 4962'.
- 8. Plug #2 (4812' 4962'), balance 12 sx inside casing. PUH to 2995'.
- 9. Plug #3 (2745' 2995'), balance 12 sx inside casing. PUH to 1355'.
- 10. Plug #4 (1205' 1355'), balance 12 sx inside casing. PUH to 400'.
- 11. Plug #5 (0' 400'), mix 31 sx to circulate good cement to surface. POH.
- 12. ND BOP & dig cellar. Cut off wellhead and top off casings as needed.
- 13. RD rig. Remove deadmen. Install dry hole marker.

14. Restore location as per BLM requirements.