

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF-078895

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Graham Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Kutz Gallup

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 6, T-27N, R-11W

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

1.

OIL ☐ GAS ☐  
WELL ☐ WELL ☒ OTHER

2. NAME OF OPERATOR

(Southwest Production Co) to: Great Western Drilling Co.

3. ADDRESS OF OPERATOR

238 Petroleum Plaza, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements\*)

See also space 17 below.)  
At surface

NE/4 NE/4 Sec 6, T-27N- R-11W

APR 02 1987

14. PERMIT NO.

15. ELEVATIONS (Show whether on, at, or above)

6017 GR

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANE

(Other)

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- #1. We wish to notify you of change of operator from Southwest Production to Great Western Drilling Co.
- #2. Cancel any and all sundry notices plans to P & A.
- #3. We plan to move in work over rig, pull and inspect 2-3/8" tubing for holes, rerun tubing with packer, set approximately 5600' swab and test the Gallup formation (5732-48 & 5799-5817), if Gallup still productive, repair hole or holes in casing and put well back on production, we hope to get this done and completed before planting time as this well is in the NAPI project.

18. I hereby certify that the foregoing is true and correct

SIGNED

*D.E. Bayler*

TITLE Superintendent

DATE April 1, 1987


(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE



\*See Instructions on Reverse Side

NMOCC