1. oil

well

below.)

2. NAME OF OPERATOR

Texaco Inc.

3. ADDRESS OF OPERATOR

AT TOTAL DEPTH:

gas

well

AT TOP PROD. INTERVAL:

REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES

X

AT SURFACE: 790' FSL & 790'FWL

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9-331-C for such proposals.)

other

P. O. Box EE, Cortez, CO 81321

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,

5. LEASE
USNM -/12020
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Kirby Gallegos
9. WELL NO. 2
10. FIELD OR WILDCAT NAME
WAW Pictured Cliff
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
26-T27N-R13W
12. COUNTY OR PARISH 13. STATE
San Juan New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
of E60 R DF
2.1
1984 (NOTE Report results of multiple Completion or Von E D
1. SEP 2 0 1984
13
BUREAU OF LAND MANAGEMENT FARMINGTON PESOURCE AREA
all pertinent details, and give pertinent dates,
rectionally drilled, give subsurface locations and to this work.)*
and abandon the subject well

ABANDON*

(other)

DIST.

BUREAU OF LAND MANAGE
FARMINGTON PESOURCE

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SUBSEQUENT REPORT_OF

Texaco Inc. requests your approval to plug and abandon the subject well as follows:

- 1. MIRUSU
- 2. Fill casing with 9.2#/gallon mud.
- 3. Spot 330' cement plug (25 sx) from 1332' to 1002'. (Perfs @ 1315 to 1332').
- 4. Spot 450' cement plug (35 sx) from 450' to surface.
- 5. Cut off casing, erect dry hole marker and clean location.

NOTE: Previous sundry notice of well completion indicated both strings of casing were cemented to surface.

Subsurface Safety Valve: Manu. and Type		Set @ Ft.
18. I hereby certify that the foregoing is true and SIGNED A. R. MARX SIGNED DY Clark Handens	TILE Field Superintendante	APPROVED AS/818#NDED
(This	space for Federal or State office use)	
ARREOVED BY	TITLE	SEP 2 1 1984
APPROVED BY TITLE DATE DATE		75/ J. Stan McKee
BLM (4) - NMOCC (3) - JNH		M. MILLENBACH Drarea Manager
•	()	

BUREAU OF LAND MANAGEMENT Caller Service 4104 Farmington, New Mexico 87499

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: #2 Kirby-Gallgos

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal Leases."
- 2. The Farmington office (telephone (505) 325-4572) is to be notified in sufficient time for a representative to witness all plugging operations.
- 3. Blowout prevention equipment is required.
- 4. In addition to normal filling of pits and cleanup of location, additional surface restoration work <u>may</u> be required, i.e. ripping of pad and/or access road, reseeding, etc. We have asked the Surface Management Agency for the surface restoration requirements for this well and we should be able to furnish you these requirements within 30 days. After plugging the well and before making final clean-up, you should contact this office unless you have already been advised as to what additional surface restoration work is required.
- 5. The following modifications to your plugging program are to be made (when applicable):

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to technical and procedural review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

Office Hours: 7:45 A.M. to 4:30 P.M.

PERMANENT ABANDONMENT OF WELLS ON FEDERAL LEASES FARMINGTON RESOURCE AREA

- 1. Secure prior approval before changing the approved plugging program.
- 2. Plugging equipment used shall have separate mixing and displacement pumps and a calibrated tank to assure proper displacement of plugs.
- 3. A proper tank or pit will be used to contain all fluids pumped from the well during plugging operations.
- 4. All cement plugs are to be placed through tubing (or drillpipe) and shall be a minimum of 15 sacks or 100 feet in length, whichever is greater.
- 5. Any cement plug placed when well is not full of fluid, or when well may be taking fluid, will be touched after cement has set to verify proper location.
- 6. Mud must be placed between plugs. Minimum consistency of plugging mud must be 9.2 lbs/gal. Brine is to be utilized for mixing mud where possible.
- 7. Within 30 days after plugging work is completed, file Subsequent Report of Abandonment, Form 3160-5 (formerly 9-331), in quintuplicate with Area Manager, Bureau of Land Management, Caller Service 4104, Farmington, New Mexico 87499. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 8. All permanently abandoned wells are to be marked with a permanent monument, on which has been stenciled or beaded the well name, well number, and well location by quarter-quarter, section, township and range. The monument is to be of steel pipe, not less than four inches in diameter, cemented permanently in the ground, and extending four feet above general ground level. The top should be closed with a screw cap, welding, or a cement plug.
- 9. After plugging work is completed:

ŧ

- a. Fill all pits, rat hole and cellar.
- b. Clean well location of all equipment, concrete bases, pipe, junk and
- c. Cut or remove tie downs.
- d. If last well on lease, and no additional drilling is contemplated, fill tank battery pits, remove battery equipment, and clean and level battery location.
- e. Accomplish surface restoration as specified by the surface management agency or land owner.

All above are minimum requirements. The Subsequent Report of Abandonment will not be approved and the period of liability under the bond of record terminated until the lease is inspected and surface work approved.

Please advise this office when the well location is ready for final inspection.

You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to technical and procedural review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.