Form 3160-5

UNITED STATES

FORM APPROVED

OCT 3 | 1997

TOTAL TARRET	DEPARTMENT OF THE INTERIOR	Budget Bureau No. 1004-0135
JUNE 1990)	BUREAU OF LAND MANAGEMENT	Expires: March 31, 1993
	DONAL OF E. H. D. F.	5. LeaseDesignation and Serial No.
	SUNDRY NOTICES AND REPORTS ON WELLS	NM-0359211
D-	not use this form for proposals to drill or to deepen or reentry to a different reservoir	6. If Indian, Allottee or Tribe Name
Do	Use "APPLICATION FOR PERMIT" for such proposals	
	Use APPLICATION TOKT ERMIT 10. State properties	7. If Unit or CA, Agreement Designation
	SUBMIT IN TRIPLICATE	
T. Type of V		
1. Type of v	Oil Gas	8. Well Name and No.
	Well Well Other	Federal 30-11
2. Name of		9. API Well No.
	Dreyfus Natural Gas Corp	30-045-24997
	and Telephone No.	10. Field and Pool, or Exploratory Area
	O Quail Springs Parkway, Suite 600 Phone (405) 749-1300	West Kutz P.C.
	of Well (Footage, Sec., T., R., M., or Survey Description	11. County or Parish, State
	VL & 990' FWL	
	W Sec. 30-27N-11W	San Juan Co., NM
14 44 14 44	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTIC	
		PE OF ACTION
	X Netice of Intent Abandonment	Change of Plans
	X Recompletion	New Construction
	Rusequent Report Plugging Back	New Construction Non-Routine Fracturing
	NOV - 5 1937 Casing Repair	Water Shut-Off
	Final Abandonment Notice Altering Casing	Conversion to Injection
		Dispose Water Dispose Water
	Other L	(Note Report results of multiple completions on Well Completion or Recompletion Report and Log Form)
	Proposed Completed Operations (Clearly state all pertinent details, and give pertinent dates: including estimated date of sta	
		Ö- o
	surface locations and measured and true vertical depths for all markers and zones pertinent to this work 1*	_
Establish	pipeline contract & recomplete to the Fruitland Coal, as follows:	
	RU WOU. Load hole w/2% KCL wtr. ND WH & NU BOPs. TOH w/1"	the & LD. RU WL. PU & RIH w/4-1/2"
A. MIK	P & set @ 1659' to abandon PC perfs. Load csg & test to 3000 psi. RIH	w/ csg gun to perforate the Fruitland
CIBI	P & set @ 1659 to abandon PC peris. Load esg & test to 5000 ps. 1611	1
Coal	1@ 1589-1606' 2 spf; 1622-33' 4 spf; Total 80 holes. WL. RU BJ. Acidize/balloff Fruitland Coal perfs via 4-1/2" csg w/500	gals 15% HCL acid & 120 - 7/8" 1.3 SG
B. RD	sealers. Est rate & pressure 8-10 BPM @ ± 1000 psi. Flush w/2% KCL	water. Surge balls & allow to fall below
balls	Sealers. Est rate & pressure 8-10 BFM @ \pm 1000 psi. Thusin W 276 Ree 2 S. Prep to frac. Treat via 4-1/2" csg @ 40 BPM & \pm 1700 psi surface tree	eating pressure. Pump + 43,000 gals
perts	s. Prep to frac. Treat via 4-1/2 csg @ 40 B1 W & 1700 par surface was 2 N2 foam (30# linear gel) & ± 80000# 20/40 Arizona Sand. RD BJ. Wa	ait 2 hours & start load recovery on choke!
		29
C. Clea	an-up frac load. Swab and/or CO as needed.	
	& RIH w/2-3/8" tbg w/production assembly. Set SN @ \pm 1585'. PU &	Kill Wish Tods & Fire State St
& N	NU wellhead. RDMO WOU.	unit Hang well on Start nump unit.
E. Set	t surface seperator, water tank, and meter loop. Build pad & install pump	Junit. Flang wert on. Start parisp age
Cle	ean up frac load. Turn well to sales.	
110	15 CARE OLFTHEL	
per	HO E: 194 For Plat TUSE	E/
14. I hereb	by certify that the foregoing is true and correct	_
Signed	Title Enginee	r Date 10/20/97

fitle

//S/ Duane W. Spencer

Conditions of approval, if any: