

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

APPLICATION FOR PERMIT TO DRILL, DEEPEN, OR PLUG BACK

1a. Type of Work DRILL	5. Lease Number NO-G-9811-1312 Unit Reporting Number
1B. TYPE OF WELL GAS	6. If Indian, All. or Tribe INDIAN ALLOTTED
2. Operator ELM RIDGE RESOURCES, INC. 505-632-3476	7. Unit Agreement Name
3. Address & Phone No. of Operator PO Box 189 Farmington, NM 87499	8. Farm or Lease Name KELLY F.C.
	9. Well Number #1-R
4. Location of Well 800' FWL, 765' FSL <small>ALL WORKS HEREIN AUTHORIZED ARE SUBJECT TO COMPLIANCE WITH ATTACHED "GENERAL REQUIREMENTS"</small>	10. Field, Pool Wildcat BASIN FRUITLAND COAL
	11. Sec., Twn, Rge, Mer. (NMPM) M SW SW SEC. 12, T27N, R13W API # 30045-31002
14. Distance in Miles from Nearest Town 13 MILES SOUTH OF FARMINGTON	12. County 13. State SAN JUAN, N.M.
15. Distance from Proposed Location to Nearest Property or Lease Line 765'	
16. Acres in Lease 160	17. Acres Assigned to Well 320
18. Distance from Proposed Location to Nearest Well, Drig, Compl or Applied for on this Lease 20'	
19. Proposed Depth 1400'	20. Rotary or Cable Tools ROTARY
21. Elevations (DF, FT, GR, Etc.) 5861' GL	22. Approx. Date Work will Start LATE FEBRUARY
23. Proposed Casing and Cementing Program SEE OPERATIONS PLAN ATTACHED	
24. Authorized by: <u>Patrick Hegarty</u> Patrick Hegarty, Agent	This action is subject to administrative procedural review pursuant to 43 CFR 3165.8 and appeal pursuant to 43 CFR 3165.4 01-25-02 Date

PERMIT NO. \_\_\_\_\_ APPROVAL DATE 2/28/02

APPROVED BY [Signature] TITLE AFM DATE 2/28/02

Archaeological Report attached

Threatened and Endangered Species Report to be submitted

NOTE: This format is issued in lieu of U.S. BLM Form 3160-3

Title 1 U.S.C. Section 1061, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or presentations as to any matter within its jurisdiction.

NOTE: This is a REDRILL well - Everything associated with this well is exactly the same as the original well that is being replaced due to down hole problems.

HOLDING FOR Change in Status to Kelly FC #1

ORIGINAL