Form 3160-5 (June 1990)

Title 18 U.S.C. Section 1001, makes it a crime for any person representations on to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget	Buri	eau	No.	100	94-0	135
Expir	es:	Ma	rch	31,	199	3

5. Lease Designation and Senal No.


SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
COMPAN	11011020	\sim	1121 01110	\sim 1.4	**

SF-078329 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6. Il Indian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT - " for such proposals 7. If Unit or CA, Agreement Designation 1. Type of Well Oil Well X Gee 8. Well Name and No. Daum LS #1 2. Name of Operator 9. API Well No. Amoco Production Company Gail M. Jefferson, Rm 1295C 3. Address and Telephone No. 3004506947 (303) 830-6157 P.O. Box 800, Denver, Colorado 80201 10. Field and Pool, or Exploratory Area Kutz Canyon Pictured Cliffs 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 660' FSL 660' FWL Sec. 32 T 28N R 9W Unit M New Mexico San Juan CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Final Abandonment Notice (Note: Report results of multiple completion Report and Log form.) 13. Describs Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) Amoco Production Company requests permission to plug and abandon the above referenced well per the attached procedures. If you have any technical questions please contact Carolanne Wyett at (303) 830-5578 or Gail Jefferson for any administrative concerns. Admin. Staff Asst. Conditions of approval, if any:

Daum LS #1
Orig. Comp.11/50
TD = 2250', PBTD = Open Hole
Page 2 of 2

- 1. Check location for anchors. Install if necessary. Test anchors.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
- 3. POOH with 1" tbg and lay down. RIH with 2 3/8" workstring and cement retainer. Set retainer at 2050'. Test casing integrity to 500#. Pull out of retainer and spot 100' plug on top. (27 cuft of cement.)
- 4. RIH with perf gun and shot squeeze holes at 1241'. RIH with tbg and retainer. Set retainer above the squeeze holes and attempt to circulate to surface. (215 cuft cement)Pull out of retainer and spot 100' cement plug on top of retainer (27 cuft cement) and spot cement inside csg from 171' to surface. (44 cuft cement) If unable to circulate besure the following is covered from 171' to surface. (47 cuft cement.)
- 4. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
- 5. Contact FMC and ship surface equipment to yard or other location per instructions.
- 6. Turn over to John Schwartz for reclamation.
- 7. Rehabilitate location according to BLM or State requirements.

DAUM LS 001 1231 Location — 32M— 28N— 9W SINGLE pc Orig.Completion — 11/50 Last File Update — 1/89 by BCB



01/17/96

To: Carolanne Wyett From: Chip Harraden Geologist -BLM

BLM FARMINGTON

Date FAX Sent: 1/17/96 FAX # 303-830 -4777

Here are the fm.tops for the	660'FSL, 660'FWL Sec. 32, 28N-9W GL 6097' ID 2250
Sanjose	
Macimiento Surface	
Ojo Alamo 1191'	
Kirtland 1296'	
Fruitland 1851	
Pictured Cliffs 2139' to TD	
Lewis	
Chacra	
Cliff House	
Menefee	
Point Lookout	
Mancos	
Gallup	
Dakota	
Carolanne,	
Hope these tops make it to	you is time. I've bean
digging out from the fun	
30 3	Thanks.
	Chip