## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices	and Reports on Wells?	7.1 2:01	<del></del>
	070 F.L		Lease Number SF-079634A
1. Type of Well GAS		6.	
	•	7.	Unit Agreement Name
2. Name of Operator  BURLINGTON  RESOURCES OTLEGE	LS COMPANY		
		8.	Well Name & Number
3. Address & Phone No. of Operator			McClanahan A #2
PO Box 4289, Farmington, NM 87	499 (505) 326-9700	9.	<b>API Well No.</b> 30-045-13069
4. Location of Well, Footage, Sec.,	T, R, M	10.	Field and Pool
1190'FSL, 1060'FWL, Sec.23, T-28			Basin Dakota
m		11.	County and State San Juan Co, NM
12. CHECK APPROPRIATE BOX TO INDICA	TE NATURE OF NOTICE, REP	ORT, OTHER	DATA
Type of Submission	Type of Action		
<del></del>	<del></del>	ange of Pl	
<del></del>	<del>-</del>	w Construc	
		n-Routine	
		ter Shut o	
	_ Altering Casing Co _ Other - Tubing repair	nversion to	o Injection
•^-	_ Other - lubing repair		
13. Describe Proposed or Complete	d Operations		-
It is intended to repair the		ll accordi	ng to the attached
procedure and wellbore	e diagram.		
	BESI	enver	
	四国级	Ell Viel	
	III MAD O		e e e e e e e e e e e e e e e e e e e
	MAR 3	1 1997	7
	Off on	370 Am	
	OIL ÇO	M. Mina	
		2.8	
			<del></del>
14. I hereby certify that the for	egoing is true and corre	ct.	
Signed Janu Drakhued (	KM2)Title <u>Regulatory Adm</u>	inistrator	_Date 3/18/97
(This space for Federal or State Of APPROVED BY	fice use)Title	Date _	143 12 0 0 0 h
CONDITION OF APPROVAL, if any:			

## **TUBING REPAIR PROCEDURE**

McClanahan A #2 DPNO: 32125A 1190' FSL, 1060' FWL M, Sec. 23, T23N, R10W, SJC, NM

Lat / Long: 36°39.86", 107°50.99"

**Project Summary:** The McClanahan A #2 has an old (1962) string of 1-1/2" tubing set @ 6230'. We suspect that this tubing has developed a hole. A wireline run on this well indicates that sand fill is covering the perforations. An impression block tagged sand fill at 6248'. We propose to hydrotest the tubing, replace any bad joints, cleanout to PBTD with a bit and air, run the tubing lower in the hole and install plunger lift equipment.

- 1. Test rig anchors, prepare blow pit. Comply to all NMOCD, BLM and BROGC safety regulations.
- 2. MIRU daylight PU with air package. Kill well with 2% KCl water. ND WH, NU BOP. Drop in with tubing to tag fill. Hydrotest tubing (test coming out of hole, due to possible hole in tubing). POOH with tubing string, replace bad joints as necessary.
- 3. PU 4-1/2" bit and cleanout to PBTD (6492') with air. Continue cleanout until sand production ceases. POOH.
- 4. RIH with 1 joint 1-1/2" tubing, SN (with plunger lift spring) and 1-1/2" tubing to approximately 6430'. ND BOP, NU WH. Blow well in. Drop plunger and kick well off. RDMO PU. Turn well to production.

Approve:	Department of the State of the
Approve:	Drilling Superintendent
Concur:	Production Superintendent

Contacts: Operations Engineer Kevin Midkiff 326-9807 (Office) 564-1653 (Pager)

Production Foreman Johnny Ellis 326-9822 (Office) 327-8144 (Pager)

## McCLANAHAN A #2


Current -- 3/10/97

DPNO: 32125A Dakota

Spud: 1st Delivered: 03/15/63 Elevation:

10/26/62 5823' KB 5813' GL

1190' FSL, 1060' FWL Unit M, Sec. 23, T28N, R10W Lat/Long: 36°39.86", 107°50.99"



## Burlington Resources Well Data Sheet

DPNO: 32125A Well Name: MCCLANAHAN A 2		#: 37093 API: 30-04	5-1306900 Formation: DK
	own: 028N Range:		uan State: New Mexico
Dual: NO Commingled: NO Curr. Compressor: No Install Date:	Prev. Compressor: Last Chg Date:	No Plunger Lift:	No BH Priority: BH Test Date: 5/13/9
CASING:			
Hole Size: $\frac{\sqrt{5}^{1}}{100000000000000000000000000000000$	.5. J.55	Longstring / Liner	Longstring / Liner
202 TO		OC: By:	TOC: By:
VELL HISTORY:		Format	tion Tops
Orig. Owner: \$\lambda \lambda \cdot \frac{\lambda \cdot \cdo	63 3 00 009 06 KT FT 193611-192110 1011 50 1101 CK	A A C V V AGOU!!# 20/40 e J	CH 5430 1  MF  PL 4230 1  GP 5274 1  GH 6128 1  GRRS  DK 6242 1
CLLING HISTORY / REMARKS:			
Last Rig Date: Last Rig AFE Type:	Last Wo	rkover:	Last WO AFE Type:
Workover Required: No Prod Ops Project Type: - Ol - Ex Toy Area Team			