Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 20, 20

5	Lease Serial No.
J.	LUASC SCHAI NO.
	NMSF - 078903
	RIVIOR - UZAMIL

SUNDRY N	OTICES AND REPORTS ON WELLS
DO NOT USE THIS	form for proposals to drill or to re-enter an
abandoned well.	Use form 3160-3 (APD) for such proposals

Do not use this form for proposals to drill or to re-enter an					NMSF - 078903	
abandoned we	6. If Indian, Allottee	6. If Indian, Allottee or Tribe Name				
SUBMIT IN TR	7. If Unit or CA/Agreement, Name and/or No.					
1. Type of Well				8. Well Name and No		
Oil Well Gas Well Ot 2. Name of Operator		CHERRY HLAVA		GALLEGOS CANYON UNIT 246		
AMOCO PRODUCTION COM 3a. Address	9. API Well No. 30-045-11688					
P.O. BOX 3092 HOUSTON, TX 77079		3b. Phone No. (include area code) Ph. 281,366.4081 Fx: 281,366.0700		10. Field and Pool, or Exploratory BASIN DAKOTA		
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)			11. County or Parish,	and State	
Sec 35 T28N R12W SWNE 1	850FNL 1450FEL			SAN JUAN COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, RI	EPORT. OR OTHE	R DATA	
TYPE OF SUBMISSION			F ACTION		. JAIA	
☑ Notice of Intent	☐ Acidize	☐ Deepen		ion (Start/D		
_	☐ Alter Casing	☐ Fracture Treat	☐ Reclam:	ion (Start/Resume)	☐ Water Shut-Off	
☐ Subsequent Report	☐ Casing Repair	□ New Construction	☐ Recomp		☐ Well Integrity	
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon	_	arily Abandon	☐ Other	
į	☐ Convert to Injection	☐ Plug Back	☐ Water D			
our well by well review to deterorduction, either in the existing reserves. That request was applied the well reserves accept our request to For technical questions please. 4. I hereby certify that the foregoing is	eview and find no further po P&A the subject well per the call Allen Kutch at 281-366	premature abandonment of the state of the st	of possible ure.			
Name (Printed/Typed) CHERRY I	/ / / //	CTION COMPANY, sent to the	i Information : ne Farmingtor	System 1		
Namc (Printed/Typed) CHERRY I	TLAVA (SWVY) ALA	va Title AUTHO	RIZED REP	RESENTATIVE		
Signature (Electronic St	ubmission)	Date 01/23/20	002			
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE US	E		
Approved By Miditions of approval, if any, are attached tify that the applicant holds legal or equi	table title to those rights in the sul		E	Date	2/8/02	
ich would entitle the applicant to conducte 18 U.S.C. Section 1001 and Title 43 U	t operations thereon.	Office	FFO			

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

^{**} ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL ** ORIGINAL **

San Juan Basin Well Work Procedure

Well Name: Version: Date: Budget: Repair Type:	GCU 246 #1 1/21/2002 DRA Plug and aband	onment		
Objectives:				
1. P&A enti	re wellbore.			
Pertinent Info				
Location: County:	Sec 35 T28N R12W San Juan		Horizon:	Basin Dakota
State:	New Mexico		API #: Engr:	30-045-11688 Allen Kutch
Lease:			Phone:	(281)366-7955
		- · · · · · · · · · · · · · · · · · · ·		
Formation To Nacimento:	ps: (Estimated formation t			
Ojo Alamo:		Menefee: Point Lookout:		
Kirtland Shale:		Mancos Shale:		
Fruitland:		Gallup:	5930	
Pictured Cliffs:	1720	Graneros:	0000	
Lewis Shale:		Dakota:	6222	
Chacra:		Morrison:		
Cliff House:	3297			
Drodonbood 3	'and lufa week'			
Test Date:	est Information: Tubing:	Casing:	RH.	

INT

CSG

Comments:

Time

5 min 10 min 15 min ВН

CSG


Plug and abandonment procedure GCU 246

- Contact Federal and State agencies prior to starting P&A work (NMOCD Charlie Perrin, 505-334-6178 X16, BLM 505-599-8907).
- 2. Check location for anchors. Install if necessary. Test anchors.
- 3. MIRUSU. Check and record tubing, casing and bradenhead pressures.
- 4. Blow down well and kill well, if necessary, with lease water.
- 5. ND wellhead. NU BOP's.
- 6. POOH with 2-3/8" tbg, visually inspecting.
- 7. TIH with CIBP on tbg. Set CIBP at 6150' to abandon the DK perfs.
- 8. Spot 12 sack cmt plug 6000' 6150' to isolate the DK.
- 9. Spot 12 sack cmt plug 5200' 5350' to isolate the GP.
- 10. Spot 12 sack cmt plug 3150' 3300' to isolate the MV.
- 11. Spot 19 sack cmt plug 1500' 1750' to isolate the PC / Fruitland.
- 12. Spot 12 sack cmt plug 250' 400' to isolate the Ojo Alamo.
- 13. Spot 12 sack cmt surface plug $0 150^{\circ}$.
- 14. ND BOP. Cut off wellhead and casing. Weld on ¼" steel plate and PXA marker.
- 15. Provide workorder to Buddy Shaw for surface reclamation.

GCU 246 P&A.DOC Page 2

GCU 246 - Proposed P&A Configuration San Juan County, NM Unit A Section 35 T28N - R12W Run 27

1-22-2002 ATK



PBTD: 6387' TD: 6423'