TYPE OR PRINT NAME

/	
Submit 3 Copies State of New Mexico Form C-103 to Appropriate District Office State of New Mexico Energy, Minerals and Natural Resources Department Revised 1-1-	
DISTRICT OIL CONSERVATION DIVISION WELL API NO. 30-039-07483	
DISTRICT II Same Pe, NM 8/303	EE X
DISTRICT III 1000 Rio Brazos Rd., Azzoc, NM 87410 6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPRIOR TION FOR FERMIN" (FORM C-101) FOR SUCH PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name	-
I. Type of Well: Ol. WELL GAS WELL	!56
2. Name of Operator	
Phillips Petroleum Company SJ 29-5 Unit #37 Address of Operator 9. Pool name or Wildeau	
3. Address of Operator 5525 Highway 64, NBU 3004, Farmington NM 87401 (STATE OF COMPANY) 9. Pool name or Wildcat Blanco Mesaverde 7231	.9
4. Well Location Court ODO Hort	
Unit Lotter L : 1800 Foot From The South Line and 990 Feet From The West	Line
Section 31 Township 29N Renge 5W NMPM Rio Arriba	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONI	MENT [
PULL OR ALTER CASING CASING TEST AND CEMENT JOB	
OTHER: Add additional pay and stimulate X OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1103.	brobosed
The Lower Lewis Shale was complete in 10/98 & plans are to now complete the Upper Lewis Shale into	erval.
MIRU. ND WH & NU BOPs. POOH w/production:tubing. Mesaverde perfs still isolated with bridge plu 5000'. RIH w/bit & scraper & tag fill. Cleanout to 5000'. RIH w/CIBP & set @ 4640'. Load hole & casing. COOH. RU Blue Jet & perf Upper Lewis Shale @ 1 spf as follows:	ıg @ L PT
4574' - 4577' (3'); 4559' - 4562' (3'); 4530' - 4533'(3'); 4521' - 4524' (3'); 4445' - 4448' (3'); 4418' - 4421' (3'); 4399' - 4402'(3'); 4354' - 4357' (3') 24 total holes	
4574' - 4577' (3'); 4559' - 4562' (3'); 4530' - 4533'(3'); 4521' - 4524' (3'); 4445' - 4448' (3'); 4418' - 4421' (3'); 4399' - 4402'(3'); 4354' - 4357' (3') 24 total holes Acidize perfs w/15% HCL & then frac well w/ 60 Quality N2 foam and sand. Flow back immediately. RIH w/bit & drill out CIBP @ 4640'. Cleanout to PBTD @ 5000'. RIH w/2-3/8" tubing and set @ 480'. ND BOP & NU WH. PT. Pump off check. Return well to production.	COOH.

TITLE MAR -4 1999