Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office		- opartment	Re	vised 1-1-89
DISTRICT I	OIL CONSERVATI	ON DIVISION		
P.O. Box 1980, Hobbs NM 88241-1980	2040 Pachec	o St.	WELL API NO.	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NM	87505	30-039-07476 5. Indicate Type of Lease	
DISTRICT III		The same of the sa	STATE LX	☐ FEE ☐
1000 Rio Brazos Rd., Aztec, NM 87410		: <u>.</u>	6State Oil & Gas Lease No. E 289-3	
SUNDRY NOTI	CES AND REPORTS ON VA	GETTAL		
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESER (FORM C-	POSALS TO DRILL OR TO DEEPEN VOIR. USE "APPLICATION FOR PI 101) FOR SUCH PROPOSALS.)	I OR PEGGENET	7. Lease Name or Unit Agreement	Name
1. Type of Well: OIL GAS WELL WELL X	OTHER C	0/17 917654 /	San Juan 29-6 Unit	009257
2. Name of Operator	D_{ℓ}	DE 3 DIV	8. Well No.	
Phillips Petroleum Company 3. Address of Operator			SJ 29-6 Unit #9	
5525 Highway 64, NBU 3004, Fa	rmington NM 87401		Pool name or Wildcat Blanco Mesaverde 72	2319
4. Well Location		~./		2313
Unit Letter M : 990	Feet From The South	Line and 990	O Feet From The WE	estLine
Section 36	Township 29N R	ange 6W	NMPM Rio Arriba	_
		er DF, RKB, RT, GR, etc.	.)	County
11. Check Apr	ropriata Roy to Indicate	NI-4		
NOTICE OF IN	propriate Box to Indicate			
MOTION OF MATERIAIDIA 10:			SEQUENT REPORT	OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CAS	ing [
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	(_
PULL OR ALTER CASING CASING CASING TEST AND CEMENT JOB				NDONMEN! L
OTHER: Add pay and stimu	late X		JENI JOB L	_
		OTHER:		L
 Describe Proposed or Completed Opera work) SEE RULE 1103. 	ions (Clearly state all pertinent deta	ails, and give pertinent date	s, including estimated date of starti	ng any proposed
MIRU. ND WH & NU BOPs. F	200H w/production tubing.	Isolate existing !	Mesaverdo ponfo with bui	das alve
MIRU. ND WH & NU BOPs. POOH w/production tubing. Isolate existing Mesaverde perfs with bridge plug. PT casing. If casing fails test - isolate failure. Remediate with cement.				
If well records indicate	oo oomout sauss that			
If well records indicate r bond log (CBL). Shoot sque the Lewis Shale.	eze holes in casing and p	s Shale interval, it oump sufficient volu	t may be necessary to rur umes of cement to cover a	n a casing and isolate
Donfonato and stimulate 41				
Perforate and stimulate the plug and run production to	e Lewis Shale (perfs to b bing. Flow test the Lewi	e determined after s Shale.	logs are run). Retrieve	pridge
A workover pit may be requ	ired.			
I hereby certify that the information above is true	and complete to the best of my knowledge	and belief.		·
SIGNATURE TALOUS C	Lue PN	D =7 = -4	Accietant	2 10 00
	тпи	Regulatory	ASSISTANT DATE	3-12-98
TYPE OR PRINT NAME Pa	tsy Clugston		TELEPHONE NO. 50	<u>5-599-3454</u>
(This space for State Use)				
APPROVED BY	ERNIE BUSCH	DEPUTY OIL & GAS INS	PECTOR, DIST. #3 AUC	1 7 1998

CONDITIONS OF APPROVAL, IF ANY: