

well file

Northwest Pipeline Corporation



PRODUCTION & DRILLING
P. O. BOX 90
FARMINGTON, NEW MEXICO 87401



October 22, 1974

repaired

Mr. A.R. Kendrick
New Mexico Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico 87410

Re: Packer leak repair
San Juan 29-6 Unit #32

Mr. Kendrick:

Northwest Pipeline Corporation has obtained the approval of partners to effect the repair of the packer leak on the subject well.

With reference to the letter of Mr. F.H. Wood dated September 10, 1974 in which he stated that the repairs would be completed on or before October 10, 1974. Northwest Pipeline Corporation has not been able to contract a rig for this work to date, however we are still trying to locate a suitable rig and will proceed with the repair job as soon as possible.

O.B. Whitenburg

O.B. Whitenburg
Drilling & Production Engineer

OBW/js

CC/ File
Well File

Northwest Pipeline Corporation



PRODUCTION & DRILLING
P. O. BOX 90
FARMINGTON, NEW MEXICO 87401

September 10, 1974

Mr. A. R. Kendrick
New Mexico Oil Conservation Commission
1000 Rio Brazos Road
Aztec, New Mexico

Re: Packer leak Repair
San Juan 29-5 Unit #32

Dear Al:

This will acknowledge receipt of your letter dated September 9, 1974, which notified us to repair the packer leak on the above captioned well.

The San Juan 29-5 Unit Operating Agreement requires that we obtain approval of partners before spending the money to effect the repair of the packer leak. We anticipate we can obtain necessary approval and complete repairs on or before October 10, 1974.

Very truly yours,

F. H. Wood, Manager
Production and Drilling

FHW/vc





OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS ROAD - AZTEC
87410

I. R. TRUJILLO
CHAIRMAN
LAND COMMISSIONER
ALEX J. ARMIJO
MEMBER
STATE GEOLOGIST
A. L. PORTER, JR.
SECRETARY - DIRECTOR

September 9, 1974

Mr. Forrest Wood
Northwest Pipeline Corporation
Room 326
Petroleum Center Building
Farmington, New Mexico 87401

Re: Northwest Pipeline Corp.
San Juan 29-5 Unit #32
N-29-29N-5W

Dear Mr. Wood:

The attached copy of the 1974 annual packer-leakage test report for the subject well indicates communication between the producible zones.

You are hereby directed to take immediate action to cause the well to be repaired to comply with Rule 112-A and the order which approved the dual completion.

If there are questions please contact us.

Yours very truly,

A. R. Kendrick
A. R. Kendrick
Engineer, District #3

Attach:
cc W/Attach.: OCC, Santa Fe, N.M.

ARK/bk