



STATE OF NEW MEXICO



ENERGY, MINERALS and NATURAL RESOURCES DIVISION  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

BRUCE KING  
GOVERNOR

ANITA LOCKWOOD  
CABINET SECRETARY

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

November 17, 1993

Mr. Richard Allred  
Phillips Petroleum Company  
5525 Highway 64 NBU 3004  
Farmington, NM 87401

RE: SJU #91, H-21-29N-06W  
SJU #40, H-23-29N-06W  
SJU #55, K-18-29N-06W  
SJU #42, G-25-29N-06W

Dear Richard:

Jim Kennedy and I retested the bradenheads on the referenced wells on Friday November 12, 1993. As enclosed copies of the retests indicate only the SJU #91 has a casing failure. In order to comply with Rule 108, Prevent Waste and Protect Fresh Water, you are hereby directed to initiate immediate remedial activity.

Tests also indicated the SJU #40 has communication between the intermediate casing and the long string. We do not ordinarily require remedial action on intermediate-longstring communication, as long as there is containment within the intermediate casing. We did not check the intermediate casing at the SJU #55 because the valve is leaking and is bullplugged. This valve should be changed out when the work can be performed in a safe manner. Although the original 1993 test was not conducted correctly on the SJU #55 it also appears to have intermediate-long string communication. The SJU #42 was okay.

If you have any questions please call me at 334-6178.

Yours Truly,

Charles Gholson  
Deputy Oil & Gas Inspector

xc: Well Files