
DEPUTYOLEGADOR

DEC 3 6 1957

Meter Number:90538
Location Name:SAN JUAN 29-6 #12A
Location:TN-29 RG-06
SC-06 UL-I
4 - Fee

NMOCD Zone: OUTSIDE Hazard Ranking Score: 00



RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone 10^{-9} to 10^{-13} cm/sec Shale 10^{-12} to 10^{-16} cm/sec Clay 10^{-12} to 10^{-15} cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.

FIELD PIT SITE ASSESSMENT FORM



GENERAL	Meter: 90538 Location: SAN JUAN 29-6 #12A Operator #: 7035 Operator Name: PAILLIPS P/L District: BLOOMFIELD Coordinates: Letter: I Section 6 Township: 29 Range: 6 Or Latitude Longitude Pit Type: Dehydrator X Location Drip: Line Drip: Other: Site Assessment Date: 5:17:94 Area: 10 Run: 51				
SITE ASSESSMENT	NMOCD Zone: (From NMOCD Maps) Inside Outside Land Type: BLM (1) State (2) Fee (3) Indian				
	Depth to Groundwater Less Than 50 Feet (20 points) □ (1) 50 Ft to 99 Ft (10 points) □ (2) Greater Than 100 Ft (0 points) □ (3)				
	Wellhead Protection Area: Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source? (1) YES (20 points) (2) NO (0 points)				
	Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) (1) 200 Ft to 1000 Ft (10 points) (2) Greater Than 1000 Ft (0 points) (3) Name of Surface Water Body				
	(Surface Water Body: Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream (1) < 100'(Navajo Pits Only)				
	TOTAL HAZARD RANKING SCORE:O POINTS				
REMARKS	Remarks: Two Pits on Location, will close only one. Pit is DRY, LOCATION. IS ON TOP OF SMITH PAIS, REDLINE AND TOPO CONFIRMED LOCATION IS DUTSIDE V.Z. DIKE IRE				
RE	PUSH 124 (SP3190) 04/08/94				

ORIGINAL PIT LOCATION	ORIGINAL PIT LOCATION Original Pit : a) Degrees from North 338° Footage from Wellhead 114' b) Length : 20' Width : 20' Depth : 4'
REMARKS	Remarks: Took Pictures at 11:04 A.M. Dump Truck - Bostmil
	Completed By: Signature Signature Sometimes and Sometimes are supported by: Signature Signature

FIELD PIT REMEDIATION/CLOSURE FORM

GENERAL	Meter: 90538 Location: SAN Juan 29-6 12A Coordinates: Letter: I Section 6 Township: 29 Range: 6 Or Latitude Longitude — Date Started: 7-14-93 Run: 10 51				
FIELD OBSERVATIONS	Sample Number(s): AK 132 Sample Depth: 12 Feet Final PID Reading 190 PID Reading Depth 12 Feet Yes No Groundwater Encountered X Approximate Depth Feet				
CLOSTIRE					
DEWADES	Remarks: Epuc lines not marked Soil Gray Strong Hyprocarbon odor Signature of Specialist: Morgan XIllian (SP3191) 03/16/8				



FIELD SERVICES LABORATORY ANALYTICAL REPORT PIT CLOSURE PROJECT - Soil

SAMPLE IDENTIFICATION

	Field ID	Lab ID		
SAMPLE NUMBER:	MK 132	945473		
MTR CODE SITE NAME:	90538	N/A		
SAMPLE DATE TIME (Hrs):	7-14-94 1359			
SAMPLED BY:		N/A		
DATE OF TPH EXT. ANAL.:	7/9/94	7/19/94		
ATE OF BTEX EXT. ANAL.:	NIA	J 14		
TYPE DESCRIPTION:	V G	Brown Sand Clay		

RESULTS	

REMARKS:

PARAMETER	RESULT	UNITS	QUALIFIERS			
PANAMETEN			DF	Q	M(g)	V(ml)
BENZENE		MG/KG				
TOLUENE		MG/KG				
ETHYL BENZENE		MG/KG				
TOTAL XYLENES		MG/KG				
TOTAL BTEX		MG/KG				
TPH (418.1)	410	MG/KG			2.12	28
HEADSPACE PID	190	PPM				
PERCENT SOLIDS	84.8186	Na %				

- TPH is by EPA Method 418.1 and BTEX is by EPA Method 8020 -

e Surrogate Recovery was at	- NIA	_% for this sample	All QA/QC was acceptable.	
irrative:				

Test Met..Jd for Oil and Grease and Petroleum Hydrocarbons in Water and Soil Perkin-Elmer Model 1600 FT-IR Analysis Report ************************ [4/0**7/19** | 15:37 Hample lientification 45673 Political areas of sension q Finisme of ample after extraction, at 1000 Teinole a eydinocendd fy jom -- 179 14d Abedesondo of Ferrocentons (1936 amil) -- 107 .1335 ាំ ៖ សេច Lieu e. ខ. ្រស្សាលច្រស់ មក នា ខេស្**ងលា**សែប ម

3000

9229

44...

129