



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

TONEY ANAYA
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-8178

May 1, 1984

Mr. Mike J. Turnbaugh
Northwest Pipeline Corp.
P.O. Box 90
Farmington, NM 87499

Re: Application for Hardship Classification
San Juan 29-5 Unit #88 G-34-29N-5W
San Juan 29-5 Unit #89 K-34-29N-5W
San Juan 29-5 Unit #90 B-34-29N-5W

Dear Mike:

The referenced applications are returned unapproved for the following reasons:

#88

- 1) The production history you supplied indicated that the well has logged off only twice in five years. After swabbing in the first time, the well returned to production at a higher rate. After swabbing in the second time, the well returned to production at a lower rate but showed increasing monthly production. This indicates that a short shut-in period may not cause permanent loss. Also, why was the well shut-in?
- 2) There is no explanation of why small bore tubing has not been installed.
- 3) There are no cost figures which indicate that without relief this well will be prematurely abandoned.
- 4) There is no documentation of water production.
- 5) Plat does not show offset ownership.
- 6) There is no signed certification.

Mr. Mike J. Turnbaugh
May 1, 1984
Page 2

#89


- 2) There is no explanation of why small bore tubing has not been installed.
- 3) There are no cost figures which indicate that without relief this well will be prematurely abandoned.
- 4) There is no documentation of water production.
- 5) Plat does not show offset ownership.
- 6) There is no signed certification.

#90

- 1) This well has been logged off only once in five years for an unusually long period of time. Why was it shut-in for this length of time? Would a shorter shut-in period of a month or several weeks cause the well to log off?
- 2) There is no explanation of why small bore tubing has not been installed.
- 3) There are no cost figures which indicate that without relief this well will be prematurely abandoned.
- 4) There is no documentation of water production.
- 5) Plat does not show offset ownership.
- 6) There is no signed certification.

If you have any questions, please contact this office.

Sincerely,



Frank T. Chavez
District Supervisor

FTC/dj

xc: Joe Ramey
Well File ✓