UNITED STATES DEPARTMENT OF INTERIOR

BUREAU OF LAND MANAGEMENT SUDRY NOTICES AND REPORTS ON WELLS	NM - 18315 /8 3/8
JUDICE INC. INC. INC. ALL VILLA ALL ALLES	
(Do Not use this form for proposedals to drill or to deepen or plug back	BI M MAIL ROUM
to a different resevoir. Use Form 3160-3 for such proposals)	7. If Unit or CA, Agreement Number
to a uniterest reservoir. Ose rotter 5100-5 for such proposato,	
Turn of Well	95 OCT AM 9: U9 8. Well Name and No.
Type of Well	29-4/CARSON 19 # 1
GAS WELL	070 FARTING APP Number
Name of Operator	
FALCON SEABOARD OIL COMPANY	30-039-24991
Address and Telephone Number	10. Field and Pool, or Exploratory Acres
C/O DAVE SIMMONS P. O. BOX 48 FARMING	
Location of Well (Sec., T., R., or Survey Description)	11. County or Parish
1910' FNL & 655' FEL	D' A '' O AIRA
Sec. 19, T29N, R4W	Rio Arriba Co., NM
. CHECK APPROPRIATE BOX(s) TO INDICATE THE NATU	
TYPE OF SUBMISSION	TYPE OF ACTION
X Notice of Intent Al	bandonment Cahnge of Plans
X Re	ecompletion New Construction
Subsequent Report Pl	lug Back Non-Routine Fracturing
Cr	asing Repair Water Shut-Off
Final Abandonment Notice	lter Casing Conversion to Injection
Oı	ther: Disposal Water
	(Note Report result of multiple completions on Well Completion or Recompletion Report and Log Form
give subsurface location and measured and true vertical depths for all markers and	zones pertinent to this work.)
perator plans to TA Fruitland zone and recomplete the Set cast iron bridge plug above Fruitland Coal forma Pressure test to 2000 psig.	ne well into the Nacimiento Formation as follows: ation inside 7" casing @3100 (Fruitland cavitated').
Set cast iron bridge plug above Fruitland Coal formal Pressure test to 2000 psig. Run corelation log from 3100-1500'. Perforate the Acidize perforations with 15% HCL and swab test. Fracture stimulate w/ 70Q Foam if required. Place Evaluate the Nacimiento formation for 6 to 9 month.	ation inside 7" casing @3100 (Fruitland cavitated'). Nacimiento over gross interval 1700 to 2900' AND SELECTIVELY. well back on production. hs.
Set cast iron bridge plug above Fruitland Coal formal Pressure test to 2000 psig. Run corelation log from 3100-1500'. Perforate the Acidize perforations with 15% HCL and swab test. Fracture stimulate w/ 70Q Foam if required. Place Evaluate the Nacimiento formation for 6 to 9 month.	ation inside 7" casing @3100 (Fruitland cavitated'). Nacimiento over gross interval 1700 to 2900' AND SELECTIVELY. well back on production. hs.
Set cast iron bridge plug above Fruitland Coal formal Pressure test to 2000 psig. Run corelation log from 3100-1500'. Perforate the Acidize perforations with 15% HCL and swab test. Fracture stimulate w/ 70Q Foam if required. Place Evaluate the Nacimiento formation for 6 to 9 month.	ation inside 7" casing @3100 (Fruitland cavitated'). Nacimiento over gross interval 1700 to 2900' AND SELECTIVELY. well back on production. hs.
Set cast iron bridge plug above Fruitland Coal formal Pressure test to 2000 psig. Run corelation log from 3100-1500'. Perforate the Acidize perforations with 15% HCL and swab test. Fracture stimulate w/ 70Q Foam if required. Place Evaluate the Nacimiento formation for 6 to 9 month.	ation inside 7" casing @3100 (Fruitland cavitated'). Nacimiento over gross interval 1700 to 2900' AND SELECTIVELY well back on production. hs. id Nacimiento based on production perforamnce. DECEIVE OCT 1 6 1995
Set cast iron bridge plug above Fruitland Coal formal Pressure test to 2000 psig. Run corelation log from 3100-1500'. Perforate the Acidize perforations with 15% HCL and swab test. Fracture stimulate w/ 70Q Foam if required. Place Evaluate the Nacimiento formation for 6 to 9 month Apply for downhole comingling of Fruitland coal and	ation inside 7" casing @3100 (Fruitland cavitated'). Nacimiento over gross interval 1700 to 2900' AND SELECTIVELY, well back on production. hs. id Nacimiento based on production perforamnce. DECEIVE OCT 1 6 1995
Set cast iron bridge plug above Fruitland Coal formal Pressure test to 2000 psig. Run corelation log from 3100-1500'. Perforate the Acidize perforations with 15% HCL and swab test. Fracture stimulate w/ 70Q Foam if required. Place Evaluate the Nacimiento formation for 6 to 9 month Apply for downhole comingling of Fruitland coal and NOTE: This format is issued in lieu of U.S. BLM Form 3160-5 I hereby certify that the foregoing is true and correspond to the standard coal and the	ation inside 7" casing @3100 (Fruitland cavitated'). Nacimiento over gross interval 1700 to 2900' AND SELECTIVELY, well back on production. hs. id Nacimiento based on production perforamnce. DECEIVE OCT 1 6 1995
Set cast iron bridge plug above Fruitland Coal formal Pressure test to 2000 psig. Run corelation log from 3100-1500'. Perforate the Acidize perforations with 15% HCL and swab test. Fracture stimulate w/ 70Q Foam if required. Place Evaluate the Nacimiento formation for 6 to 9 month Apply for downhole comingling of Fruitland coal and NOTE: This format is issued in lieu of U.S. BLM Form 3160-5 I hereby certify that the foregoing is true and corresponding to the summand of the summan	ation inside 7" casing @3100 (Fruitland cavitated'). Nacimiento over gross interval 1700 to 2900' AND SELECTIVELY. well back on production. hs. id Nacimiento based on production perforamnce. DECEIVE OCT 1 6 1995 rect DIST. 3
Set cast iron bridge plug above Fruitland Coal formal Pressure test to 2000 psig. Run corelation log from 3100-1500'. Perforate the Acidize perforations with 15% HCL and swab test. Fracture stimulate w/ 70Q Foam if required. Place Evaluate the Nacimiento formation for 6 to 9 month Apply for downhole comingling of Fruitland coal and NOTE: This format is issued in lieu of U.S. BLM Form 3160-5 I hereby certify that the foregoing is true and corresponding to the summand of the summan	Assimination inside 7" casing @3100 (Fruitland cavitated'). Nacimiento over gross interval 1700 to 2900' AND SELECTIVELY. Well back on production. hs. Id Nacimiento based on production perforamnce. DECEVE OCT 1 6 1995 TITLE AGENT DATE: 10
Set cast iron bridge plug above Fruitland Coal formal Pressure test to 2000 psig. Run corelation log from 3100-1500'. Perforate the Acidize perforations with 15% HCL and swab test. Fracture stimulate w/ 70Q Foam if required. Place Evaluate the Nacimiento formation for 6 to 9 month Apply for downhole comingling of Fruitland coal and NOTE: This format is issued in lieu of U.S. BLM Form 3160-5 I hereby certify that the foregoing is true and corresponding to the summand of the summan	ation inside 7" casing @3100 (Fruitland cavitated'). Nacimiento over gross interval 1700 to 2900' AND SELECTIVELY. well back on production. hs. id Nacimiento based on production perforamnce. DECEIVE OCT 1 6 1995 rect DIST. 3
Set cast iron bridge plug above Fruitland Coal formal Pressure test to 2000 psig. Run corelation log from 3100-1500'. Perforate the Acidize perforations with 15% HCL and swab test. Fracture stimulate w/ 700 Foam if required. Place Evaluate the Nacimiento formation for 6 to 9 month Apply for downhole comingling of Fruitland coal and NOTE: This format is issued in lieu of U.S. BLM Form 3160-5 I hereby certify that the foregoing is true and corresponding to the summand of the summand	A P PROVI

NMOCD