

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTSUBMIT IN DUPLICATE*
(See other instructions on reverse side)FOR APPROVED
OMB NO. 1004-0137

Expires: December 31, 1991

WELL COMPLETION OR RECOMPLETION REPORT AND LOG*

1a. TYPE OF WELL: OIL WELL ☐ GAS WELL ☒ DRY ☐ Other ☐		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
b. TYPE OF COMPLETION: NEW WELL ☒ WORK OVER ☐ DEEP-EN ☐ PLUG BACK ☐ DIFF. RESVR ☐ Other ☐		7. UNIT AGREEMENT NAME San Juan 29-7 Unit	
2. NAME OF OPERATOR BURLINGTON RESOURCES OIL & GAS COMPANY		8. FARM OR LEASE NAME, WELL NO. San Juan 29-7 Unit #61B	
3. ADDRESS AND TELEPHONE NO. PO Box 4289, Farmington, NM 87499 (505) 326-9700		9. API WELL NO. 30-039-26135	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements)* At surface 1385'FNL, 890'FWL At top prod. interval reported below At total depth R-10987A		10. FIELD AND POOL, OR WILDCAT Blanco Mesaverde	
11. SEC., T., R., M., OR BLOCK AND SURVEY OR AREA Sec. 34, T-29-N, R-7-W		12. COUNTY OR PARISH Rio Arriba	
13. STATE New Mexico		14. PERMIT NO. DATE ISSUED	
15. DATE SPUDDED 6-29-99		16. DATE T.D. REACHED 7-4-99	
17. DATE COMPL. (Ready to prod.) 9-2-99		18. ELEVATIONS (DF, RKB, RT, BR, ETC.)* 6761 GR, 6771 KB	
19. ELEV. CASINGHEAD		20. TOTAL DEPTH, MD & TVD 6088	
21. PLUG. BACK T.D., MD & TVD 6084		22. IF MULTIPLE COMPL. HOW MANY*	
23. INTERVALS DRILLED BY 0-6088		24. PRODUCTION INTERVAL (S) OF THIS COMPLETION-TOP, BOTTOM, NAME (MD AND TVD)* 4463-5970 Mesaverde	
25. WAS DIRECTIONAL SURVEY MADE		26. TYPE ELECTRIC AND OTHER LOGS RUN CBL-CCL-GR	
27. WAS WELL CORED No		28. CASING RECORD (Report all strings set in well)	
29. LINER RECORD		30. TUBING RECORD	
31. PERFORATION RECORD (Interval, size and number)		32. ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.	
33. PRODUCTION		34. DISPOSITION OF GAS (Solid, used for fuel, vented, etc.) To be sold	
35. LIST OF ATTACHMENTS None		36. I hereby certify that the foregoing and attached information is complete and correct as determined from all available records	

SIGNED

TITLE Regulatory Administrator

DATE

ACCEPTED FOR RECORD
9-23-99

*(See Instructions and Spaces for Additional Data on Reverse Side)

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department of agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOC

FARMINGTON FIELD OFFICE
BY

multi-story, level, increasing up (recovered):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENT, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Ojo Alamo	2546'	2725'	White, cr-gr ss.	Ojo Alamo	2546'	
Kirtland	2725'	3028'	Gry sh interbedded w/tight, gry, fine-gr ss.	Kirtland	2725'	
Fruitland	3028'	3505'	Dk gry-gry carb sh, coal, grn silts, light-med gry, tight, fine gr ss.	Fruitland	3028'	
Pictured Cliffs	3505'	3630'	Bn-Gry, fine grn, tight ss.	Pic. Cliffs	3505'	
Lewis	3630'	4108'	Shale w/siltstone stringers	Lewis	3630'	
Huerfanto Bentonite*	4108'	4461'	White, waxy chalky bentonite	Huerfanto Bent.	4108'	
Chacra	4461'	5032'	Gry fn grn silty, glauconitic sd stone w/drk gry shale	Chacra	4461'	
Cliff House	5032'	5342'	ss. Gry, fine-grn, dense sll ss.	Cliff House	5032'	
Menefee	5342'	5691'	Med-dark gry, fine gr ss, carb sh & coal	Menefee	5342'	
Point Lookout	5691'	6088'	Med-light gry, very fine gr ss w/frequent sh breaks in lower part of formation	Pt. Lookout	5691'	

Perforations continued:
 5403, 5449, 5520, 5529, 5569,
 5573, 5575, 5672, 5687, 5694,
 5699, 5702, 5705, 5713, 5714,
 5718, 5722, 5724, 5741, 5749,
 5759, 5767, 5770, 5777, 5783,
 5819, 5834, 5881, 5900, 5910,
 5959, 5970

*Huerfanto Bentonite is the legal top of Mesa Verde in New Mexico (North of the Chacra line)