

Re: Gallegos Canyon unit #2 K 35-29N-¹²~~13~~W API # 30-045-07661

This well was leaking and the local farmer had someone weld the crack to stop the fluid from running into his field. This is a residential area and they are building more and more homes. This well had pressure on it, had been leaking and has no casing below 272'. We deemed it necessary to plug this well under emergency plugging operations to protect life, health, and the environment.

Charlie T. Perrin