

The Pinkstaff Estate #2 was drilled and plugged

in 1952. The well has started flowing fresh water to the surface. The plugging procedure used did not separate two aquifers which contain different qualities of water. The well needs to be reentered and plugged to separate these waters and stop the surface water flow.

Exhibit #1 shows a sketch of the wellbore on page one, location map and photo on page two, and a proposed plugging program on page three.