



STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

BRUCE KING  
GOVERNOR

LARRY KEHOE  
SECRETARY

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

October 9, 1979

Mr. Woodrow Stiles  
% Roy L. Cook Estate  
402 Hermosa Drive S. E.  
Albuquerque, New Mexico 87108

Re: Roy L. Cook	Roy L. Cook
Pan American State Com #1	Gale #1
K-23-29N-11W	M-13-29N-11W

Dear Woodrow:

As per our conversations, both subject wells have similar situations with suspected casing failures. In order to return both wells to producing status the casing would have to be tested and repaired. The Pan American State Com #1 would require additional testing, perforating and cement, to repair the water flow from the casing to the surface. Plugging the wells would require a cement plug from Total Depth to 100' above the perforations, a cement plug from below the Ojo Alamo formation to above it, and a cement surface plug. Again, the Pan American State Com #1 would require repair of the water flow. Contact this office before starting any plugging program.

Yours truly,

Frank T. Chavez  
Deputy Inspector

FTC:no