Form 3160-5 (November 1983) (Formerly 9-331)	ovember 1983) (Other Instructions on				n re-			
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)						6. IF INDIAN, ALLOTTEE OR TRIBE NAME NA		
OIL GAS X OTHER						7. UNIT AGREEMENT NAME		
2. NAME OF OPERATOR					8	S. FARM OR LEASE NAME		
Texaco Inc. Operator for Texaco Producing Inc. 3. ADDRESS OF OPERATOR						Mexico Federal N		
P. O. Box EE Cortez, Co. 81321 1. LOCATION OF WELL (Report location clearly and in accordance with any State requirements See also space 17 below.) At surface						#1 10. FIELD AND POOL, OR WILDCAT Basin Dakota		
	1850' FNL & 1650' FWL BUREAU OF LAND MANAGEMENT 15. BLEVATIONS (Show whether DF, RT, DM, VERTES OURCE AREA 5631' GL				.	Sec 15, T29N, R11W		
14. PERMIT NO.		15. BLEVATIONS (Show whether DF, R	T. GH. ARESOLIDO MANAGEMENT		2. COUNTY OR PARISE	13. STATE	
			5631 G	L AREA	Şá	an Juan	N.M.	
16.	Check Ap	propriate Box T	o Indicate Na	ture of Notice, Report,	or Oth	er Data		
	NOTICE OF INTENTION TO:					EQUENT REPORT OF:		
TEST WATER SHUT- FRACTURE TREAT		CLL OR ALTER CASI Ultiple completi	11	WATER SHUT-OFF FRACTURE TREATMENT		REPAIRING '		
SHOOT OR ACIDIZE	-	BANDON*		SHOOTING OR ACIDIZING	,	ABANDONME	[
REPAIR WELL	[X] c	HANGE PLANS				multiple completion		
17. DESCRIBE PROPOSED of proposed work. nent to this work.	f well is direction	ATIONS (Clearly st nally drilled, give	tate all pertinent subsurface location	details, and give pertinent on and measured and true	dates, in	on Report and Log fo cluding estimated da- lepths for all marker	te of starting any	
School and Procedure 1) MIRUSU 2) Kill w 3) TOOH w 4) TIH w/ 5) TIH w/ 6) TIH w/ 7) Set pk Pump 2 Tail. 8) TIH & 9) TOOH w 10) TIH w/ Annulu	d presents used will ell with /tubing bit & cle packer and thru tubi r at 1275 80 sxs 50 Circulat DOC press /RBP tubing an	s a possil l be as for 3% KCl anout fil d RBP Set ng gun an ', establ -50 pozmi e cement ure test d product	ole hazer ollows: l if nece RBP at l d perfora ish circu x lead sl to surfac casing to	te 4½" casing lation and cem curry followed e. WOC. 1000 psi.	at 1 ment by 5	MARA ON ON A00'. as follows 0 sxs class	75 1987 V. DIV.	
11) Return	well to	producing	Status.	RDM050	; !	ACODA	WED	
18. I hereby certify that the foregolog is true and correct SIGNED					ent	рать 3-18-87		
(This space for Federal or State office use)						MAD-2 ()	1987	
APPROVED BY TITLE TOTAL CONDITIONS OF APPROVAL, IF ANY:						DATE		
BLM (4) NMOGCC (2) JNH - LAA - AAK - MLK Sull Tex 3-25-25 Phlance *See Instructions on Reverse Side						FARMINGTON HESSON AND AND A		
" BLM "	Steve Mason	erne L	8 . \$ 5. 10 ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° °	: Shale and willfully to ma	ike to s	ny denastment or o	agency of the	