

Submit 3 Copies
to Appropriate
District Office

3 NMOCD
1 File
1 Conoco

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-045-08865
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-11242
7. Lease Name or Unit Agreement Name Southwest Mounds Com
8. Well No. 1
9. Pool name or Wildcat Basin Dakota
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5455' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL, OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐
2. Name of Operator
Dugan Production Corp.

3. Address of Operator
P.O. Box 420, Farmington, NM 87499

4. Well Location
Unit Letter C : 870 Feet From The North Line and 1790 Feet From The West Line
Section 2 Township 29N Range 14W NMPM San Juan County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug by spotting Class B + 6% gel plugs as follows:

1. 100' plug across Dakota top @ 5647'.
2. 100' plug across Gallup p top @ 5042'.
3. Perforate 50' below Mesa Verde top @ 2050' and spot 100' plug inside and outside 4 1/2" casing. (IF FLUID REMAINS STABLE, NO TAG)
4. Perforate 50' below Pictured Cliffs top @ 1052' and spot plug to cover Fruitland top @ 792'. (SAME AS #3)
5. Perforate 50' below surface casing @ 250' and circulate cement to surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John Alexander TITLE Operations Manager DATE 6/30/92
TYPE OR PRINT NAME John Alexander TELEPHONE NO.

(This space for State Use)

Original Signed by CHARLES GHOLSON

APPROVED BY DATE

CONDITIONS OF APPROVAL, IF ANY: