

F. Loc. 1090/N; 1162/E

Elev. 6393

Spd. 10-26-65 Comp.

TD 7745

PB 7718

Casing S. 13 3/8 @ 119 W 100 Sx. Int. 7 @ 4806 W 200 Sx. Pr. 4 1/2 @ 7745 W 22 3/8 Sx. T. 2 3/8 @ 7451

Csg. Perf.

Prod. Stim.

SWF

7488-7702

2267 ACF

I.P. 2213 BO/D MCF/D After 3 Hrs. SLP 225/PSI After Days GOR Grav. 1st Del. 5-5-66

TOPS	NITD	Well Log	TEST DATA							Ref. No.
Kirtland	C-102	Plat	Schd.	PC	Q	PW	PD	D		
Fruitland	C-103	Electric Log								
Pictured Cliffs	C-104 3 1/4	C-110 3-14-66	1/23/67	1443	117	544	722	106		
Cliff House	7-5-66	C-122	1/10/68	1454	70	504	727	62		
Menefee	Ditr	Dfa	7/21/69	894	79	452	447	79		11
Point Lookout	Datr	Dac	9/28/70	979	76	449	490	73		
Mancos	Remarks: Abandoned Lak 4-28-84 Abandoned Greenhorn Deck on Top 8-14-84 Done Abandoned		7/21/71	802	27	357	401	26		
Gallup			7/31/72	782	68	293	391	61		
Sanostee			9/4/73	725	62	275	363	56		
Greenhorn			11/2/75	840	24	275	420	21		1/11
Dakota 26 7420										
Morrison	MC-1697									
Entrada	R-2994									
	E-320									
Sh. Lat. -1032										

P
o
n

Jan. | Feb. | Mar. | Apr. | May | June | July | Aug. | Sept. | Oct. | Nov. | Dec. |