

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**Lease No. **078500**Unit **Woodriver**

SUNDRY NOTICES AND REPORTS ON WELLS

| | | | |
|--|--|--|----------|
| NOTICE OF INTENTION TO DRILL | | SUBSEQUENT REPORT OF WATER SHUT-OFF | |
| NOTICE OF INTENTION TO CHANGE PLANS | | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL | | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | | SUBSEQUENT REPORT OF ABANDONMENT | |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | | Water Fracture | X |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 21, 1956

Well No. **2** is located **1455** ft. from **[N]** line and **1750** ft. from **[E]** line of sec. **9****NE Section 9**

(¼ Sec. and Sec. No.)

30N

(Twp.)

Se

(Range)

MEPM

(Meridian)

Blanco

(Field)

San Juan

(County or Subdivision)

New Mexico


(State or Territory)

The elevation of the derrick floor above sea level is **6263** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

2-16-56 Total Depth 5482'. FBTD 5025'.
Water fractured Cliff House perforated intervals 4865' - 4872', 4925' - 4932',
4950' - 4950' with 52,520 gallons water and 48,700# sand. Breakdown pressure
1950#, maximum pressure 1950#, average treating pressure 1600#. Injection
rate 50 bbls./min. Flush 5800 gallons.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Company**Address **Box 997****Farmington, New Mexico**By *Will McLaughlin*Title **Petroleum Engineer**