Form 3140-5 (June 1990)

or representations as to any matter within its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUBMIT IN TRIPLICATE

PORM APPROVED
Budget Bureau No. 1001-0135
Expires: March 31, 1993

5.	Lowe	Dy	(n	Ltica	and	Sorial	No.
		_					

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

14-20-0603-9591 6. If Indian, Allottee or Tribe Name Navajo

7. If Unit or CA, Agreement Designation

TARMINGTON DISTARCT CHARGE

CY 211

1. Type of Well					
	·	8. Well Name and No.			
Name of Operator		North Hogback 1 #22			
Raymond T. Duncan		9. API Well No.			
Address and Telephone No.					
P. O. Box 420, Farmington,	, NM 87499 (505) 325-1821	10. Field and Pool, or Exploratory Area			
Location of Well (Footage, Sec., T., R., M., or Survey De	escription)	Slickrock Dakota 11. County or Parish, State			
2036' FNL & 2280' FWL					
Unit F, Sec. 1, T29N, R17W	v	San Juan, NM			
	s) TO INDICATE NATURE OF NOTICE, RE	PORT, OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACT	TYPE OF ACTION			
Notice of Intent	Abandonment	Change of Plans			
	Recompletion	New Construction			
Subsequent Report	Plugging Back	Non-Routine Fracturing			
	Casing Repair	Water Shut-Off			
Final Abandonment Notice	Altering Casing	Conversion to Injection			
.]	x Other <u>Cut off casing</u>	Dispose Water (Note: Report results of multiple completion on Well			
		Completion or Recompletion Report and Log form.)			
	perunent octains, and give perunent dates, including estimated date of s all depths for all markers and zones pertinent to this work.)*				
give subsurface locations and measured and true vertical	al depths for all markers and zones pertinent to this work.)*	omplete 3-23-94.			
give subsurface locations and measured and true vertical	al depths for all markers and zones pertinent to this work.)*				
give subsurface locations and measured and true vertical	al depths for all markers and zones pertinent to this work.)*	omplete 3-23-94.			
give subsurface locations and measured and true vertical	al depths for all markers and zones pertinent to this work.)*				
give subsurface locations and measured and true vertical	al depths for all markers and zones pertinent to this work.)*	OR COR DIV			
Cut of casing at 3.	below ground level. Job co				
Cut of casing at 3. Thereby certify that the foregoing is true and correct Signed	depths for all markers and zones pertinent to this work.)* below ground level. Job co	916 COM DIV			
Cut of casing at 3. Cut of casing at 3. I hereby certify that the foregoing is true and correct Signed	below ground level. Job co	903 (300) DIV6 903 (500) DIV6 5/10/94			
Cut of casing at 3' I hereby certify that the foregoing is true and correct Signed	depths for all markers and zones pertinent to this work.)* below ground level. Job co	916 COM DIV			

*See Instruction on Reverse Side