## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Not	ices and Reports on Well	s	<del></del>
		5.	Lease Number SF-065557A
I. Type of Well GAS		6.	
		7.	Unit Agreement Name
2. Name of Operator			
BURLINGTON BESOURCES	& GAS COMPANY		
OIL & GAS COMPANT		8.	
3. Address & Phone No. of Operator		9.	Cornell #3R API Well No.
PO Box 4289, Farmington, NM 87499 (505) 326-9700		9.	30-045-29539
4. Location of Well, Footage, Sec., T, R, M		10.	Field and Pool
1190'FEL, 1450'FSL, Sec.1, T-29-N, R-12-W, NMPM		11	Fulcher Kutz PC County and State
		11.	San Juan Co, NM
	The state of the s	DEDODE OTHER	DATA
12. CHECK APPROPRIATE BOX TO IN Type of Submission	DICATE NATURE OF NOTICE Type of Ac	, REPORT, OTHER	DATA
X Notice of Intent	_X_ Abandonment	Change of Pl	
 Subsequent Report	Recompletion _ Plugging Back _	New Construc Non-Routine	
Subsequent Report	Casing Repair	Water Shut o	ff
Final Abandonment	Altering Casing _ Other -	Conversion t	o Injection
It is intended to plug an procedure and wellbore 8/31/2001.		ell according t to submit this	o the attached procedure is
700 FIE 31 M 9: 48		Constant of the second of the	
14. I hereby certify that the Signed Ammy Wimself (This space for Federal or Standard RAPPROVED BY	for Title Regulator	correct.  ry Supervisor Date	ate 8/30/01 TLW 9/18/01
CONDITION OF APPROVAL, if any: Title 18 U.S.C. Section 1001, makes it a crime for United States any false, fictitious or fraudulent	any person knowingly and willfully to statements or representations as to any	make to any department or matter within its juriso	agency of the diction.

# PLUG AND ABANDONMENT PROCEDURE

08/28/01

#### Cornell #3R

AIN #6393701

Fulcher Kutz Pictured Cliffs 1450' FSL and 1190' FEL, Section 1, T29N, R12W San Juan County, New Mexico, API #30-045-29539 Lat: 36 - 45.0906'/Long: -108 - 2.6748'

All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- 1. Test location rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and Burlington safety regulations. Conduct safety meeting for all personnel on location. RU rig and equipment. ND wellhead and NU BOP, test BOP.
- TOH and LD 1-1/2" tubing, total 2025'.
- 3. Open bradenhead valve. Establish rate down 3-1/2" casing with 30 bbls water, record pump rate and pressure. Monitor bradenhead for flow. If no flow or blow, then pump 24 7/8" RCN balls in an additional 30 bbls water and monitor pressure, rate and volumes pumped, to confirm perforations are taking water and there is not a casing leak. If the bradenhead flows water or there are other indications of a casing leak then use 1-1/2" tubing from well to plug the well.
- 4. Plug #1 (Pictured Cliffs perforations and Fruitland, Kirtland and Ojo Alamo tops, 2041' - Surface'): Establish rate into PC perforations with water. Mix and pump 110 sxs cement (long plug, 30% excess) down the 3-1/2" casing, do not displace. Double valve and shut in well. WOC. Tag cement, use wireline unit if necessary. Fill casing as necessary.
- 5. ND cementing valve and cut off wellhead. Fill 3-1/2" casing and annulus with cement as necessary. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.

ineer Approval: Druce W. Down 9-29-01

Drilling Superintendent

Contacts: Operations Engineer

Joe Michetti

Pager: 564-7187

Approved: Y Office - 326-9764

Sundry Required: (YES

Regulătory Approval

JAM/plh

# Cornell #3R

#### Current AIN #6393701

# Fulcher Kutz Pictured Cliffs

Today's Date: 08/28/01

Spud: 4-11-98

Completed: 5-4-98

Elevation: 5829' GL 5839' KB

SE, Section 1, T-29-N, R-12-W, San Juan County, NM

API # 30-045-29539

Lat: 36 - 45.0906'/Long: -108 - 2.6748'

Circulated 16 bbis Cement to Surface

8-3/4" hole

7 " 20# J-55 Casing set @ 131' Cmt w/53 cf (Circulated to Surface)

Ojo Alamo @ 626'

Kirtland @ 760'

Fruitland @ 1794'

Pictured Cliffs @ 1990'

1-1/2" Tubing set @ 2025' (62 joints, 2.9#, J-55)

Pictured Cliffs Perforations: 1991' - 2041' (16 holes)

6-1/4" hole

TD 2203'

PBTD 2163'

3-1/2" 9.3#, J-55 Casing set @ 2193' Cement with 741 cf Circulated Cement to Surface

# Cornell #3R

## Proposed P&A

AIN #6393701

Today's Date: 08/28/01

Spud: 4-11-98

Completed: 5-4-98

Elevation: 5829' GL

5839' KB

8-3/4" hole

6-1/4" hole

Fulcher Kutz Pictured Cliffs

SE, Section 1, T-29-N, R-12-W, San Juan County, NM

API # 30-045-29539

Lat: 36 - 45.0906'/Long: -108 - 2.6748'

Circulated 16 bbls Cement to Surface

7 " 20# J-55 Casing set @ 131'
Cmt w/53 cf (Circulated to Surface)

Plug #1 2041' - Surface Cement with 110 sxs (long plug, 30% excess)

Ojo Alamo @ 626'

Kirtland @ 760'

Fruitiand @ 1794'

Pictured Cliffs @ 1990'

PBTD 2163'

TD 2203'

Pictured Cliffs Perforations: 1991' – 2041' (16 holes)

3-1/2" 9.3#, J-55 Casing set @ 2193' Cement with 741 cf Circulated Cement to Surface