

DISTRICT I 1 Conoco  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210-

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

# OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-11571
7. Lease Name or Unit Agreement Name Stella Needs a Com
8. Well No. 1
9. Pool name or Wildcat Basin Dakota

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/>	2. Name of Operator Dugan Production Corp.
3. Address of Operator P.O. Box 420, Farmington, NM 87499	4. Well Location Unit Letter <u>K</u> : <u>1650</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>West</u> Line Section <u>36</u> Township <u>30 N</u> Range <u>14 W</u> NMPM <u>San Juan</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5592' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug by spotting Class B + 6% gel plugs as follows:

1. 100' plug across Dakota top @ 5850.
2. 100' plug across Gallup top @ 4990.
3. 100' plug across Mesa Verde top @ 2800'.
4. Perforate 50' below Pictured Cliffs top @ 1252' and spot plug inside and outside 4 1/2" casing to cover Fruitland top @ 1098'.
5. Perforate 50' below surface casing @ 268' and circulate cement to surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John Alexander TITLE Operations Manager DATE 6/30/92  
TYPE OR PRINT NAME John Alexander TELEPHONE NO.

(This space for State Use)

Original Signed by CHARLES GHOLSON

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE JUN 30 1992

CONDITIONS OF APPROVAL, IF ANY:

Change Step 3 - Perforate 4 1/2" casing @ 2800' & Set 100' Plug IN & OUTSIDE casing.