

F. Loc. 1650/N; 1090/E Elev. 6331 DF Spd 6/9/52 Comp. 12/5/52 TD 5450 PB
 Casing 9-5/8 @ 177 W 115 Sx. Int. _____ @ _____ W _____ Sx. Pr. 7 @ 4677 W 300 Sx. T. 2 1/2 @ 5438
 Csg. Perf. _____ Prod. Stim. _____
 Shot 1635 qts 4757-5457
 I.P. 8656 ~~XXXX~~ MCF/D After 3 Hrs. Sic. P. 1099 PSI After 43 Days GOR _____ Grav. _____ 1st Del. 8/27/53 T
r
a
n
s
f
e
r EPNG

TOPS		NIID	X	Well Log	X	TEST DATA						
Kirtland		C-102		Plat	X	Schd.	PC	Q	PW	PD	D	AIL
Fruitland	2760	C-103		Electric Log	X							
Pictured Cliffs	3060	C-104	X	C-110	X		934	1663	580	467	1931	
Cliff House	4708	Remarks G 1190 MCF Natural										
Menefee	4896											
Point Lookout	5254											
Mancos												
Tockto												
Dakota												
Morrison												
Entrada												

P. _____
 Blanco MV Co. San Juan S 33 T 30N R 8W U H Oper. EPNG Lsc. Gartner No. 4