UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

			14 2
Sundry Not	ices and Reports on Well	S	
	10 To	91077	Lease Number
	<i>X</i> ≥ × 1		SF-278128
Type of Well		6.	If Indian, All. o
GAS	FEB	2000	Tribe Name
	BEO	EIVED S	
	- 	ONT OIL	Unit Agreement Na
Name of Operator	C S	6T.3	
BURLINGTON	\\$\\\$_\\$\\\	a little	
RESOURCES OIL	& GAS COMPANY	1317 (13 July 20)	
		. 8 مستعطاعات	Well Name & Numb
Address & Phone No. of Opera			TURNER #1
PO Box 4289, Farmington, N	M 87499 (505) 326-9700	9.	
			300450922600
Location of Well, Footage, S		10.	Field and Pool
90'FNL 990' FEL Sec. 28, T-30	-N, R-09-W, NMPM	a -	Blanco PC/Blanco
		11.	County and State
			San Juan Co, NM
. CHECK APPROPRIATE BOX TO I	NDICATE NATIBE OF NOTICE	REPORT OTHER	DATA
Type of Submission	Type of Act		DAIA
X Notice of Intent		Change of Pl	ang
_ <u>x</u> _ Notice of intent		_ New Construc	
Subsequent Report	Plugging Back	Non-Routine	
bubsequent keport	Casing Repair	Water Shut o	_
Final Abandonment	Altering Casing		
Final Abandonment	X Other - Re-Stimula		.5 111,0001011
	n ocher ne bermare		
B. Describe Proposed or Com	pleted Operations		
1. Pull 1 1/2" tbg.			
2. Set CIBP above Mesa	Verde perforations.		
Set RBP above Pictur			
 Pressure test casing 			
	ictured Cliffs perforation		
6. Run packer and frac	string. Set packer above	e Pictured Clif	ffs perforations.
Acidize and fracture	stimulate Pictured Clif	fs formation.	
8. Clean out wellbore.			
9. Run 2-3/8", 4.70#, J	-55, EUE tubing and set	approximately	4,860`.
10. Return well to produ	ction.		
10. Return well to produ	ection.		
4. I hereby certify that the	ne foregoing is true and	correct.	
signed leggy (ale	Title Regulatory Ad	ministrator_Da	te 1/13/00
This space for Federal or Sta PPROVED BY MAN COLUMN BE	nte Office use) GCNATA Title	Date	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Turner #1

Spud: 10/26/50
Workover History:
(12/7/60) Ran 5-1/2" liner, then ran
5-1/2" csg to surface and cmt'd to
surface. Perfed and fraced PC and
MV
(11/17/82) Pkr leak. Pulled tubing
and pkr and re-ran tubing and pkr

Tapacito Pictured Cliffs / Blanco Mesaverde Unit A, Section 28, T30N, R9W Rio Arriba County, NM Elevation: 5865' GL, 5872' KB

LAT: 36° 47.23' / LONG: 107° 46.79'

