

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER	6. IF INDIAN, ALIEN OR TRUST NAME
2. NAME OF OPERATOR El Paso Natural Gas Company	7. UNIT ACCESSION NAME
3. ADDRESS OF OPERATOR P. O. Box 289 Farmington, New Mexico 87401	8. FARM OR LEASE NAME Morris A
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface R. 11W, T. 29N, R. 11W	9. WELL NO. #2
11. COUNTY OR PORTER (See instructions)	10. FIELD AND POOL, OR WILDCAT Ateco PC
12. COUNTY OR PORTER (See instructions)	11. WELL, T. R., M. OR FIELD NO. SURVEY OR ALIAS
13. COUNTY OR PORTER (See instructions)	12. COUNTY OR PORTER (See instructions)

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

1. TO ABANDON WELL

2. TO REPAIR WELL

3. TO REPAIR Casing

4. TO REPAIR Wellhead

5. TO REPAIR Wellbore

6. TO REPAIR Casing

7. TO REPAIR Wellhead

8. TO REPAIR Wellbore

9. TO REPAIR Wellhead

SUBSEQUENT REPORT OF:

1. TO ABANDON WELL

2. TO REPAIR WELL

3. TO REPAIR Casing

4. TO REPAIR Wellhead

5. TO REPAIR Wellbore

6. TO REPAIR Casing

7. TO REPAIR Wellhead


8. TO REPAIR Wellbore

9. TO REPAIR Wellhead

(Note: Report results of multiple completion, or well completion or recompletion. Report and location.)

17. If the well is to be abandoned, state all pertinent details and give pertinent dates, including estimated date of completion. If the well is to be repaired, state all pertinent details and give pertinent dates, including estimated date of completion. If the well is to be repaired, state all pertinent details and give pertinent dates, including estimated date of completion.

Pull 1" tubing and replace with 2" work string. Spot cement plug in open hole from 1950' to TD with 50 sxs. Pull up above Ojo Alamo and perforate squeeze holes at 740'. Squeeze with 50 sxs cement leaving 100' casing. Pull out of hole. Perforate squeeze holes at 152'. Pressure place 40 sxs cement into formation and up to surface. Set dry hole marker.



18. I hereby certify that the foregoing is true and correct

SIGNED

John J. Teller

TITLE

Production Engineer

DATE

4-19-79

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

*See Instructions on Reverse Side

NM OCC

MAR 6 1981
James F. Sims
JAMES F. SIMS
DISTRICT OIL & GAS SUPERVISOR