

Mr. Doyle Baxter
February 21, 1983
Page two

~~6.~~ Jose Jaquez #1, K-24-30N-12W

Fire wall needs to be built up. Water and oil inside fire wall needs to be picked up and disposed of. Leaking 3" valve on load line. Tank has run over and needs to be cleaned.


7. Ruby Coriscott #1, C-25-30N-12W

Oil inside firewall needs to be picked up and salvaged if possible. Tank has run over and needs to be cleaned.

You are hereby directed to initiate remedial action as soon as possible.

If you have any questions please call this office.

Yours truly,



Charles Gholson
Deputy Inspector

CG:gc

cc: Dick Stamets
Reading file
Operator file

