UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Repor	M. 11.		
	rts on wells آ 5- والمروب	21 4: 14	
Type of Well GAS	DEG!	5.	Lease Number SF-078200-8 If Indian, All. Tribe Name Unit Agreement N
Name of Operator	AUG	13 1998	Onic Agreement r
RESOURCES OIL & GAS COMPANY Address & Phone No. of Operator		M. DIV.	Well Name & Numb
PO Box 4289, Farmington, NM 87499 (505)	326-9700	9.	API Well No. 30-045-09390
Location of Well, Footage, Sec., T, R, M		10	. Field and Pool
810'FNL 1180'FEL, Sec.23, T-30-N, R-10-W,	NMPM		Blanco P.C.
		11	. County and State
			San Juan Co, NM
CHECK APPROPRIATE BOX TO INDICATE NATURE	OF NOTICE, R	EPORT, OTHE	R DATA
Type of Submission T	ype of Action	n	
X Notice of Intent Abandonm	ent	Change of P	lans
Recomple	tion	New Constru	ction
Subsequent Report Plugging	Back	Non-Routine	Fracturing
Casing R	epair	Water Shut	off
Final Abandonment Altering	Casing	Conversion	to Injection
X Other -R	estimulate		
	· · · · · · · · · · · · · · · · · · ·		
Describe Proposed or Completed Operatio	ns		
It is intended to restimulate the Pictu in the following manner:	red Cliffs f	ormation of	the subject well
in the following manner:			-
in the following manner: Move in rig up. Clean out the pl	lug back tota	l depth at	3140′.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat	lug back tota the Pictured	l depth at	3140′.
in the following manner: Move in rig up. Clean out the pl	lug back tota the Pictured	l depth at	3140′.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat	lug back tota the Pictured	l depth at	3140′.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat	lug back tota the Pictured	l depth at	3140′.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat	lug back tota the Pictured	l depth at	3140′.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat	lug back tota the Pictured	l depth at	3140′.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat	lug back tota the Pictured	l depth at	3140′.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat	lug back tota the Pictured	l depth at	3140′.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat	lug back tota the Pictured	l depth at	3140′.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat	lug back tota the Pictured	l depth at	3140′.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat Clean out and return well to pro	lug back tota the Pictured oduction.	l depth at Cliffs for	3140′.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat Clean out and return well to pro	lug back tota the Pictured oduction.	l depth at Cliffs for	3140′.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat Clean out and return well to pro	lug back tota the Pictured oduction.	l depth at Cliffs for	3140'.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat Clean out and return well to pro	lug back tota the Pictured oduction.	l depth at Cliffs for	3140'.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat Clean out and return well to pro	lug back tota the Pictured oduction.	l depth at Cliffs for	3140'.
in the following manner: Move in rig up. Clean out the pl Acidize and foam fracture treat Clean out and return well to pro	lug back tota the Pictured oduction.	l depth at Cliffs for	3140'. mation. Date 8/4/98

Riddle B #4 **Pertinent Data Sheet**

API#: 300450939000

Location: 810 'FNL & 1180 'FEL, Unit A, Section 23, T30N, R10W, San Juan County, New Mexico

Latitude: 36 ° - 48.16 '

Longitude: 107 ° - 50.9 '

Field: Blanco PC

Elevation: 6,408 'GL

TD: 3.158 **PBTD:** 3,140' 6,418 'KB

DP#: 50626A

Spud Date: 8/10/62

Compl Date: 10/1/67

Lease: NM 203300

Initial Potential: 1059 Mcfd

<u>GWI:</u> 100 %

NRI: 84 %

Original SIP: 624 psi

Prop#: 12567900

Casing Record:

Hole Size (In.)	Csg Size (In.)	Wt. (#'s) & Grade	Depth Set (Ft.)	Cement (Sx.)	Cement (Top)
12 1/4	9 5/8	43.5 S-95	116	75	circ to surf
6 3/4	2 7/8	6.4 J-55	3,158	150	2406' @ 75% eff.

Tubing Record:

Tbg. Size Tubingless"

Wt. & Grade

Depth Set

Joints

Comments

Formation Tops:

Ojo Alamo:

1,765

Kirtland Shale: 1,857

Fruitland: Pictured Cliffs: 3,025'

2,675'

Logging Record:

ELEC

Original Stimulation: Perf'd 3028-32', 3048-52', 3062-66' w/36 Holes, SWF w/ 29,900 gal wtr and 30,000# 10/20

sand

Workover History:

Production History:

5/98 PC capacity: 35.0 MCF/D. 5/98 PC cum: 931.0 MMCF.

Pipeline:

EPNG

Filfe: Q:\area\!pcteam\1998\welldata\slimhole\SLIMPERT

Riddle B #4

Section 23 A, T-30 -N R-10 -W San Juan, New Mexico

Blanco Pictured Cliffs Field Wellbore Schematic

