Form 9-531

SHOOT OR ACIDIZE

REPAIR WELL

## SUBMIT IN TRIPLICATE. UNITED STATES

Porming provide

ABANDONMENT\*

	Bud pet				
LEASE	DLAGN.	AT 10 N	3500	MILLA	. No.
			- /		

( .) i . i . i 	DEPARTMENT OF THE INTERIOR (Other Instructions on re-	5. LEADE DESIGNATION AND SERVER. NO.	
	GEOLOGICAL SURVEY	SF_085244_1	
	SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IP INDIAN, ALBOYLIEL OR TRIBE NAME	
1.	OIL GAS OTHER	7. UNIT AGRELMENT NAME	
2.	NAME OF OPERATOR	8. FARM OR CEASE NAME	
	Tenneco Oil Company	Riddle	
3.	ADDRESS OF OPERATOR	9. WELL NO.	
	P. O. Box 1714, Durango, Colorado 81301	#2	
	LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  See also space 17 below.)  At surface	Blanco Mesaverde  11. Enc., T., E., M., OR BLM. AND SULVEY OR AREA	
	790 FSL, 1850 FWL, Unit N		
		Sec. 17, T-30-N, R-9-W	
14.	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH TO. STATE	
	6083 Gr.	San Juan New Mexico	
16.	Check Appropriate Box To Indicate Nature of Notice, Report, or C	other Data	
	NOTICE OF INTENTION TO:	ENT REPORT OF:	
	TEST WATER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF	REPAIRING WELL ALTERING CASING	
	TO CONTROL TREATMENT	ADIDITIO CANTO	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Recomplete Mesaverde (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

ABANDON\*

CHANGE PLANS

SHOOTING OR ACIDIZING

We plan to rig up completion rig, and recomplete Mesaverde zone as follows: Run tbg and set drillable 7" cmt retainer above casing shoe and squeeze open hole interval w/350 sx cmt. Dress off cmt plug to approximately 10' below 7" csg shoe. Set 3° knuckle joint and kick off hole. Drill 6-1/4" hole 50' through Mesaverde formation. Drilling operations will limit hole deviation to less than 1-1/2° per 100 feet and maximum to 12-14°. Run IES, Gamma Ray-Density, and hole caliper across open hole. Run 4-1/2" OD casing, 11.6# w/stage collar approximately 500' above the top of the Mesaverde inside 7" csg. Cmt volume calculated from caliper log to fill annular space from TD to 500' inside 7" csg. Perf Point Lookout and frac. Set CIBP above Point Lookout and perforate Cliff House and Menefee sections. Frac. Run tbg, drill out BP. Will run deliverability test.

OIL CON. COM. 18. I hereby certify that the foregoing is true and correct Than DATE \_May. M. K. Wagner (This space for Federal or State office use) TITLE APPROVED BY . CONDITIONS OF APPROVAL, IF ANY: 5 USGS \*See Instructions on Reverse Side 1 Aztec Oil and Gas

1 Cont.

1 File