

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

SF 078125-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Delhi. Turner

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Blanco Mesa Verde

11. SEC., T., R., M., OR BLK. AND

Sec. 18, T-30-N, R-9-W
N.M.P.M.

12. COUNTY OR PARISH

San Juan

13. STATE

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

Post Office Box 4289 Farmington, NM 87409

4. LOCATION OF WELL (Report location clearly and in accordance with all State requirements. See also space 17 below.)

At surface 1780'S, 660'W

BUREAU OF LAND MANAGEMENT

FARMINGTON RESOURCE AREA

6357'GL

14. PERMIT NO.

15. ELEVATIONS (Show where well is located)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Sidetrack, Case, Cement & Frac XX

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

In order to increase production it is planned to workover and restimulate this well in the following manner: Pull tbg, set a drillable bridge plug near the bottom of the 7" casing & pressure test to 1000 psi. If tbg is stuck, cut off tbg approximately 100' below the 7" casing shoe, set a drillable cmt retainer near the bottom of the 7" csg, squeeze the open hole w/approximately 200 sks cmt. Pressure test the 7" csg to 1000 psi. Isolate & squeeze cmt any leaks. If leaks are squeezed near the base of the Ojo Alamo, no additional block squeeze of the 7" annulus is planned. If there are no leaks near the base of the Ojo Alamo, perforate two squeeze holes @ the base of the Ojo Alamo & block squeeze the 7" annulus w/approximately 125 sks cmt. CO if hole conditions permit, otherwise sidetrack & drill to approximately 5750'. Run a full string of 4 1/2" production csg & sufficient amt of cmt to tie into the 7" csg shoe. Selectively perforate & sandwater frac the Mesa Verde formation.

RECEIVED

NOV 07 1985

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Drilling Clerk

DATE

11-4-85

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

OIL CON. DIV.
APPROVED

NOV 06 1985

FARMINGTON RESOURCE AREA

*See Instructions on Reverse Side

NMOCC