

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

W. P. 09867-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Lunt

9. WELL NO.

66

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 17, T-30N, R-13W

12. COUNTY OR PARISH 13. STATE

San Juan

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

R & G Drilling Co., Inc.

3. ADDRESS OF OPERATOR

P.O. Box 327, Farmington, N.M. 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1690' PSI, 990' PSI
Sec. 17-130N-113W 5.5 Sec. 1.403.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, ST, CR, etc.)

5600'

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Round trip 2" tbg. and replace 1 bad joint. Sting into packer. Seal assembly O...
2. Squeeze Dakota perf's 6181-6052 with 35 sx to 2000 psi. Pull tbg. out of Pak. Spot 5 sx on top Pak.
3. Pull tbg. spotting 15 sx plug 5110-5260' and 15 sx plug 3750'-3900'.
4. Cut and pull 4 1/2 casing @ 3500'.
5. Spot 35 sx plug 3550-3450', spot 53 sx plug 2900'-3050', spot 35 sx plug 1375'-1475', spot 15 sx plug 240'-195' spot 10 sx surface plug. Weld on plate 3' below surface.

UNRECORDED

DEC 8 1966

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

