

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-024158

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

30-12 C

9. WELL NO.

#9

10. FIELD AND POOL, OR WILDCAT

Blanco Fruitland

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 9, T30, R12

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER2. NAME OF OPERATOR
NORTHWEST PRODUCTION CORP.3. ADDRESS OF OPERATOR
P.O. BOX 1796, EL PASO, TEXAS 799494. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1800' FNL, 990' FEL, Sec 9, T30, R12, Unit H

14. PERMIT NO.

15. ELEVATIONS (Show whether PF, RT, GR, etc.)

5779' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)


(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Plan to plug and abandon well as follows.

1. Spot cement to cover 20' above perforations.
2. Perforate at 615' and circulate cement to surface. If cement
will not circulate will squeeze in 50 sacks cement at 615'
and squeeze 30 sacks cement down braden head.
3. Spot 15' cement plug in surface and place dry hole marker.

Do not plan to recover any casing.

APR 13 1970



18. I hereby certify that the foregoing is true and correct

SIGNED

Charles E. Weimer

TITLE

Manager Production Operations 4-10-70

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side