

Mr. Doyle Baxter  
February 21, 1983  
Page two

6. Jose Jaquez #1, K-24-30N-12W

Fire wall needs to be built up. Water and oil inside fire wall needs to be picked up and disposed of. Leaking 3" valve on load line. Tank has run over and needs to be cleaned.


7. Ruby Corscott #1, C-25-30N-12W

Oil inside firewall needs to be picked up and salvaged if possible. Tank has run over and needs to be cleaned.

You are hereby directed to initiate remedial action as soon as possible.

If you have any questions please call this office.

Yours truly,



Charles Gholson  
Deputy Inspector

CG:gc

cc: Dick Stamets  
Reading file  
Operator file