

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-4909

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Yah Mabs Pah

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Savage

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Harcoschen-Gallup

11. SEC., T., E., M., OR BLK. AND  
SURVEY OR AREA

Sec. 2, T30N, R16W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. NAME OF OPERATOR <b>EPROC ASSOCIATES</b>	
3. ADDRESS OF OPERATOR <b>P. O. Box 776, Durango, Colorado 81301</b>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <b>660 feet from South line, 1870 feet from East line</b>	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>5515 Ground</b>

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

☒

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to cement the existing perforations with sufficient cement  
to cover by 50 feet.  
Pull out production casing possible and cement 50 feet above and  
50 feet below stub.  
Put in surface plug.  
Erect marker.  
Clean up location.  
Fill in pits.



18. I hereby certify that the foregoing is true and correct

SIGNED

*RE Smith*

TITLE

Agent

DATE

July 25, 1967

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side