

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator James Hatcher of Bloomfield Oilfield Service		8. Farm or Lease Name Monsanto State E
3. Address of Operator Box 1641 Bloomfield, New Mexico 87413		9. Well No. 1
4. Location of well UNIT LETTER <u>E</u> <u>1980</u> FEET FROM THE <u>N</u> LINE AND <u>660</u> FEET FROM <u>2</u> T30N R16W THE <u>W</u> LINE, SECTION <u>2</u> TOWNSHIP <u>T30N</u> RANGE <u>R16W</u> NMPM.		10. Field and Pool, or Wildcat Horseshoe Gallup
15. Elevation (Show whether DF, RT, GR, etc.)		12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>


17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Move equipment on location, Rig up and pump into well @ rate or 4 bbl. per min. Insert pump down plug and displace to 1394, mixed and pump 20 sk plug followed by wiper plug, displace plug to 1390. W.O.C. overnight. Run in and tag plug, plug at 1360, Perforated casing at 350, mix and pump 45 sk plug, circ cement to surface, Cut off well head and installed dry hole marker with 10 sk cement.

Cleaned and leveled location, ready for inspection. 6-23-82

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James Hatcher TITLE pres. DATE 6-24-82



APPROVED BY _____ TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE _____

CONDITIONS OF APPROVAL, IF ANY: