	UNITED STATES DEPARTMENT OF THE INTERI	SUBMIT IN TRIPLICATE* (Other instructions on reverse side)	Form approved Budget Bureau 5. LEASE DESIGNATION AT SF 030212	No. 42-R1424. VD SERIAL NO.
SUI (Do not use thi	GEOLOGICAL SURVEY IDRY NOTICES AND REPORTS (form for proposals to drill or to deepen or plug b Use "APPLICATION FOR PERMIT—" for such p	ack to a different reservoir.	6. IF INDIAN, ALLOTTEE	
OIL GAS WELL WELL	OTHER		7. UNIT AGREEMENT NAM	IS .
well well other NAME OF OPERATOR Thomas A. Dugen			8. FARM OR LEASE NAME Malco Copple 9. WELL NO.	
Box 234, Furnington, N. M. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface				
			Verde Gallup 11. SEC., T., R., M., GR BLE. AND	
1650	fnl 1900' fel, Sec. 6, T30N,	, 115W	SURVEY OR AREA	risv. 1947
4. PERMIT NO.	15. ELEVATIONS (Show whether DF	F, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
	53691 DF		San Juan	R. M.
6.	Check Appropriate Box To Indicate N		Other Data JENT REPORT OF:	
TEST WATER SHUT FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED	NOTICE OF INTENTION TO: OFF PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS OR COMPLETED OPERATIONS (Clearly state all pertine) If well is directionally drilled, give subsurface local	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results Completion or Recomp	ALTERING W. ALTERING CAS ARANDONMENT of multiple completion of the completion of	n Well
nent to this work) *		· · · · · · · · · · · · · · · · · · ·	
nent to this work	Plugged and abandoned Feb., I Pulled tubing and rods. Squeezed open hole with 30 sm Shot off recoverable casing. Spotted 21 sx cement - 50' in Spotted 34 sx plug 700' to 80 Plugged surface pipe w/5sx. of Erected dry hole marker.	c cement and filled 25 and 50° out of casis 30° at base of Messayes	ig stub.	12 ≠ 5½* 08(
nent to this work	Plugged and abandoned Feb., I Pulled tubing and rods. Squeezed open hole with 30 sm Shot off recoverable casing. Spotted 21 sx cement - 50° in Spotted 34 sx plug 700° to 80 Plugged surface pipe w/5sx.	c cement and filled 25 and 50° out of casis 30° at base of Messayes	ig stub.	
nent to this work	Plugged and abandoned Feb., I Pulled tubing and rods. Squeezed open hole with 30 ar Shot off recoverable casing. Spotted 21 ax cement - 50' in Spotted 34 ax plug 700' to 80 Plugged surface pipe w/5ax. of Erected dry hole marker.	and 50' out of casing of at base of Messaver coment.	ng stub. rde fermation.	ED
nent to this work	Plugged and abandoned Feb., I Pulled tubing and rods. Squeezed open hole with 30 ar Shot off recoverable casing. Spotted 21 ax cement - 50' in Spotted 34 ax plug 700' to 80 Plugged surface pipe w/5ax. of Erected dry hole marker.	c cement and filled 25 and 50° out of casis 30° at base of Messayes	RECEIVE	E D

TITLE _

APPROVED BY ________ CONDITIONS OF APPROVAL, IF ANY:

DATE ___